Wrong Location

9-53

STATE	COMPANY
Kansas	Lance Hill
COUNTY	FARM / WELL NO.
Sumner	Credit / 1
BLOCK	SURVEY
SEC. 1	
T. 33 / R. 3E	TOTAL DEPTH 3435'
	SE-SE-SE
	COMMENCED
	COMPLETED
	REMARKS
ALTITUDE 1109	
PRODUCTION D&A	

CASING RECORD

SHOT	QUARTS	BETWEEN

FORM 186 - In stock and for sale by Ross-Martin Co., Tulsa

Should be SE-SE-NE 1-34s-2E

Ohio Called questioning this location

Samples Start @ 2200'

2200 — ng sh, sdy sh. Stalnaker Sst 2275
ng sh, g-bf, fos
bf, g-f, sdy sh.
ng sh.
Stal 75 — g, f-med-g, subv micac sst.
interbedded ng sh.

2300 — sst is co. grained in part
ng sh.

2400 — gritty in part

g-bf, d-f.
g, med, g, subv micac, sst.
bf, dse lst
ng sh, sdy sh.

2500 — gbf, d-f.
ng sh.

2600 — med to dk. g. sh.
dk. g to blk sh.
ng sh. Layton Sst? 2689
Ke 89 — g, f-med, g subv micac, calc sst
"
ng sh
Lay 40 — g, f-g, subv micac sst
porous & clustered in part
interbedded ng sh

2800 — sst is co. grained in part
ng sh. KC 2868
bf to brn. f. fos.
pr. por in gbff. fos. lst

2900 — g, f, fos.
sl. oos, por. at base
c. bf, d-f, fos, porous in part

g-bf, d-f.
lt. g, dse
g, f, f, fos. ool. lst
g, f-g, subv micac calc sst
ng sh, sdy sh
g, s, f, same as above
ng sh
g-bf, d-f.
brn. f. fos.

3100 — "gbf, d-f.
lt. g, dse
c-g, d-f
"
ng sh.

3200 — g, f-g, subv micac sst
dg, g sh.

bf, d-f.
dg, g, sh, f
dk. d to blk sh.
g, f, g, subv micac sst.

3300 — g, dg to blk sh
brn, f, fos, lst
med g to dk. g, sh
brn dse lst
v. col. sh
g, f, g, tight micac, calc, sst
v. col. sh. PBC 3402
Coal 02 — ng sh. & v. col. A
Miss 08 — wh. to g, med xln. dy lst ML 3408

3500

3600

3700 — T.D. 3435'

3800

3900