



TRILOBITE TESTING INC.

P.O. Box 1733 • Hays, Kansas 67601

Test Ticket

NO. 041292 15316

Well Name & No. Hennan #8-1 Test No. 1 Date 1-21-11
 Company I A Operating, Inc Elevation 2183 KB 2175 GL
 Address 9915 W 21st North, Suite B, Wichita, Ks. 67205
 Co. Rep / Geo. Randy Killian Rig Maverick #108
 Location: Sec. 8 Twp. 14S Rge. 20W Co. Ellis State Ks

Interval Tested 3462 - 3514 Zone Tested LKC A-C
 Anchor Length 52' Drill Pipe Run 3460 Mud Wt. 8.7
 Top Packer Depth 3457 Drill Collars Run 0 Vis 48
 Bottom Packer Depth 3462 Wt. Pipe Run 0 WL 7.2
 Total Depth 3514 Chlorides 1200 ppm System LCM 2#
 Blow Description IFP - Weak Blow, 1"
ISI - Dead
FFP - Dead
FSI - Dead

Rec	Feet of	%gas	%oil	%water	%mud
<u>6</u>	<u>Mod w/oil Seum</u>				
Rec	Feet of	%gas	%oil	%water	%mud
Rec	Feet of	%gas	%oil	%water	%mud
Rec	Feet of	%gas	%oil	%water	%mud
Rec	Feet of	%gas	%oil	%water	%mud

Rec Total 6 BHT 100 Gravity _____ API RW _____ @ _____ °F Chlorides _____ ppm
 (A) Initial Hydrostatic 1694 ☒ Test 1125 T-On Location 1:10
 (B) First Initial Flow 28 ☐ Jars _____ T-Started 2:26
 (C) First Final Flow 32 ☐ Safety Joint _____ T-Open 4:10
 (D) Initial Shut-In 928 ☐ Circ Sub _____ T-Pulled 6:15
 (E) Second Initial Flow 30 ☐ Hourly Standby _____ T-Out 8:45
 (F) Second Final Flow 32 ☒ Mileage 32 RT x 2 80 Comments Released
 (G) Final Shut-In 455 ☐ Sampler _____ 36 hours after
 (H) Final Hydrostatic 1620 ☐ Straddle _____ last test

Initial Open 5 ☐ Ruined Shale Packer _____
 Initial Shut-In 60 ☐ Ruined Packer _____
 Final Flow 30 ☐ Extra Packer _____
 Final Shut-In 30 ☐ Extra Recorder _____
☒ Day Standby 12 hours 5800 Sub Total 2005
☐ Accessibility _____ MP/DST Disc't _____
 Sub Total 2005

Approved By _____ Our Representative Jana Mc Lemmon

Triobite Testing Inc. shall not be liable for damaged of any kind of the property or personnel of the one for whom a test is made, or for any loss suffered or sustained, directly or indirectly, through the use of its equipment, or its statements or opinion concerning the results of any test, tools lost or damaged in the hole shall be paid for at cost by the party for whom the test is made.

620-542-1008 Rig 108

Thank You