


Map No. **KANSAS** Sec. 35 Twp. 26 R. 1^W
Well No. 1- Petrie Farm
O.C. Johnson Company

NORTH

WEST

EAST



SOUTH

Location _____

Drilling Remarks _____

Rig Up _____

Drilling Remarks _____

RECORD

Cased _____ in. _____ ft.
Sand _____
Gas _____
Oil _____
Total Depth _____

PRODUCTION

1st 24 hrs. Nat. _____
1st 24 hrs. after shot _____
Gas _____ cu. ft. _____
Dry Hole _____
Abandoned _____

Map No. **KANSAS** Sec. 35 Twp. 26 R. 1^w
Well No. 1- Petrie Farm
J.C. Johnson Company

NORTH

Ft. from N. Line

330 Ft. from S. Line

Ft. from E. Line

330 Ft. from W. Line

1930

WEST

EAST

SOUTH

Date

REPORT

3/5

Loc

3/12

Bldg. rig.

3/19

Picking up.

3/26

Hdly 750'

4/2

" 1800'

4/9

" 2325'

4/16

U/R 8" 2855'

4/23

3077 U.R. 8"

4/30

Top Shat 3090'

5/7

77W 3170 Hdly 3185'

5/14

Base Mississippi line

3385' Run 15" 3438'

HFW 3470

Telco 3485-3540

Telc line 3541

TD 3541

Dry & Abandoned

Map No. **KANSAS** Sec. 35 Twp. 26 R. 14Well No. 1 PetrieT. C. Johnson Company

Contractor

SECTION PLAT

Ft. from N. Line

320 Ft. from S. Line

Ft. from E. Line

330 Ft. from W. Line

FIRST REPORTS

Location ✓

Rig up

Drilling and Remarks:

RECORD

Cased.....in.,ft.

Sand.....

Gas.....

Oil.....

Total Depth.....

PRODUCTION

1st 24 hrs. Nat.....

1st 24 hrs. after shot.....

Gas.....Cu. Ft.

Dry Hole.....

Abandoned.....

Date

MAR 5 - 1930

192

S. J. LEWIS Scout

Map No. **KANSAS** Sec. 25 Twp. 26 R. 1WWell No. 1 PeterT. C. Johnson Company

Contractor

SECTION PLAT

Ft. from N. Line

330 Ft. from S. Line

Ft. from E. Line

330 Ft. from W. Line**ABANDONED**

Location

Rig up

Drilling and Remarks:

NW 3470Wilcox 8455-3540Sil 3541

RECORD

Cased.....in.,ft.

Sand.....

Gas.....

Oil.....

Total Depth 3541

PRODUCTION

1st 24 hrs. Nat.....

1st 24 hrs. after shot.....

Gas.....Cu. Ft.

Dry Hole.....

Abandoned.....

Date

MAY 14 1930**S. J. LEWIS**

Scout