

** WC

Field

WC

State Kansas

County Stanton

Company J. M. Huber Corp.

Farm Hooper Garner

Well No. 1

Sec. 21

Twp. Blk.

30S

Range Survey

42W

fr N

fr E

fr S

fr W

of C NE $\frac{1}{4}$

Contractor Huber Tools

(Symm Fo)

Remarks

Miss Test

Comm. 3-5-55

Comp. 4-20-55

Elev. 3518

T. D. 5546

P. B.

Pay

I. P.

D & A

R. P.

Casing Record: 13 3/8

7

20 10 3/4

5 1/2

16 85/8 1526/2400

Summ. 100

3-2-55 LOC

Tops

man fm 5000

MAR

9 1955

105 cm 1230

Keep 5332

Spotted 200 sur cm

Lung 2700

WOC

Top 3260

MAR

16 1955

CO & DD to 1293

Lung 3560

Spotted 450 sur cm

4 stages

CO & DD to 1528

Ø 2213

MAR

23 1955

TTD 3806 SD for surm

MAR

30 1955

loss cm @ 4060

Ø #1 5312-62 rec #2 50'

5' blk bottom sh.

9' v fine glauco tite sd.

4' sh

32' sd w/ little por bleeding some gas

btm 1' had bubbles of oil

DST #1 5320-62 op 70 min

shaky W to no gts

rec 200' v sh gcm @ 790's lig csw

FP 0-200 BH 1225/15

Ø 5413

APR 6 - 1955

TTD 5546 stuck DP

WOO

APR 13 1955

~~TTD DP~~

RTD 5546 log?

DST (str. phn.) 5367-82 ph. failed

DST 5367-82 - hole bridged in test
conditions hole

DST 5369-84 (str. phn.) open H. hrs.

Sl. 610 sec 140' SW FP 105-105

BH 1275/20

D & A hold factors

Schl. (H. hrs.)

Top 3174

Lang 3478

Mud sh 4985

Mud 5414

