
Harper

KANSAS

SECTION 15 TOWNSHIP 31S RANGE 9W

WELL NO. #1 Walter Miller

COMPANY The Texas Co.



FORM 504-3 SUNRAY

S-513-A

CO. Harper ELEV.

SEC. 15 TWP. 31 RGE. 9W

COMPANY The Texas Co. NO. 1

FARM Walter Miller

LOC. C SW NW

GEOL.

CONTR.

POOL Spivey-Grabs

SPUD

Location

OCT 2 [illegible]

FIRST REPORT

CO. LSE. NO. SEC. TWP. RGE.

S-513-A

CO. Harper ELEV. 1643

SEC. 15 TWP. 31 RGE. 9W

COMPANY The Texas Co. NO. 1

FARM Walter Miller

LOC. C SW NW

NOV 20 57

ABANDONED

CO. LSE. NO. SEC. TWP. RGE.

L 3676
Bkc 4192
M 4408

TD ~~4445~~ 4440

GEOL.

CONTR.

POOL Spivey-Grabs

SPUD 9-29-57

Location OCT 8 57

8" 356/

Ø 3305

9-29-57 DST 4411

-20 60" G/20"

160' SO & GCM

BHP 1500/30" PST 4422-40

60" G/30" 110' O & GCM

240' SW BHP 1280/30" TD 4440

5½ 4440 w/c Co 4420

28/ 4409-16 190 12g MPH

250A 1½ BF/d 1 hrs

$7.90 49gw p/h 18 hrs NOV 5 57

$7.80 $43BW 24 hrs

16/ 4384-88 frac & Ld

NOV 20 57 TD 4441 D&A