

TRILOBITE TESTING INC.

P.O. Box 1733 • Hays, Kansas 67601

Test Ticket

NO. 040032 **15271**

Well Name & No. Slipke #25-1 Test No. 1 Date 1-5-11
 Company Maralex Resources Elevation 2680 KB 2818 GL
 Address 755 Goddard Ave P.O. Box 338 Ignacio Co 81137
 Co. Rep / Geo. John Randlel Rig Falcon
 Location: Sec. 25 Twp. 6S Rge. 26W Co. Sheldon State Ks

Interval Tested 3840 3900 Zone Tested LKC-J
 Anchor Length 60 Drill Pipe Run 3706 Mud Wt. 8.9
 Top Packer Depth 3835 Drill Collars Run 117 Vis 52
 Bottom Packer Depth 3840 Wt. Pipe Run -0- WL 7.2
 Total Depth 3900 Chlorides 900 ppm System LCM 2#

Blow Description IF: weak blow, died in 13 mins

ISI: No blow back over 30.

FF: No blow over 30 mins

FBI: No blow back over 60 min

Rec	Feet of	%gas	%oil	%water	%mud
<u>20</u>	<u>mud</u>			<u>100</u>	

Rec Total 20 BHT 105 Gravity _____ API RW _____ @ _____ °F Chlorides _____ ppm

(A) Initial Hydrostatic	<u>1908</u>	☒ Test	<u>1125</u>	T-On Location	<u>18:00</u>
(B) First Initial Flow	<u>18</u>	☒ Jars	<u>250</u>	T-Started	<u>18:55</u>
(C) First Final Flow	<u>23</u>	☒ Safety Joint	<u>75</u>	T-Open	<u>21:40</u>
(D) Initial Shut-In	<u>1617</u>	☐ Circ Sub		T-Pulled	<u>11:55</u>
(E) Second Initial Flow	<u>23</u>	☐ Hourly Standby		T-Out	<u>2:37</u>
(F) Second Final Flow	<u>28</u>	☒ Mileage <u>50x2 = 100x1.25</u>	<u>125</u>	Comments	
(G) Final Shut-In	<u>1069</u>	☐ Sampler			
(H) Final Hydrostatic	<u>1853</u>	☐ Straddle		☐ Ruined Shale Packer	

Initial Open 15
 Initial Shut-In 30
 Final Flow 30
 Final Shut-In 00

Sub Total 1575

Approved By _____ Our Representative Chuck [Signature]


Sub Total 1575

Sub Total 1575

MP/DST Disc't _____

Trilobite Testing Inc. shall not be liable for damaged of any kind of the property or personnel of the one for whom a test is made, or for any loss suffered or sustained, directly or indirectly, through the use of its equipment, or its statements or opinion concerning the results of any test, tools lost or damaged in the hole shall be paid for at cost by the party for whom the test is made.

785-259-3188



TRILOBITE TESTING INC.

P.O. Box 1733 • Hays, Kansas 67601

Test Ticket

NO. 040033

Well Name & No. Strike #25-1 Test No. 2 Date 1-6-11
 Company Maralex Elevation 2620 KB 2612 GL
 Address 755 Goddard Ave P.O. Box 338 Ignacio Co. 81137
 Co. Rep / Geo. John Runderl Rig Falcon
 Location: Sec. 25 Twp. 6S Rge. 26W Co. Sheridan State KS

Interval Tested 3900 3930 Zone Tested LKE-K
 Anchor Length 30 Drill Pipe Run 3761 Mud Wt. 9.0
 Top Packer Depth 3885 Drill Collars Run 117 Vis 48
 Bottom Packer Depth 3900 Wt. Pipe Run -0- WL 7.2
 Total Depth 3930 Chlorides 900 ppm System LCM 2#

Blow Description IF: weak blow, built to 1/2 in. over 15 min

ISI: No blow back over 30 min

FF: No blow over 30 min.

FSI: No blow back over 60 min

Rec	Feet of	%gas	%oil	%water	%mud
<u>20</u>	<u>mud with oil specs.</u>				
Rec	Feet of	%gas	%oil	%water	%mud
Rec	Feet of	%gas	%oil	%water	%mud
Rec	Feet of	%gas	%oil	%water	%mud
Rec	Feet of	%gas	%oil	%water	%mud

Rec Total 20 BHT 103 Gravity _____ API RW _____ @ _____ °F Chlorides _____ ppm

(A) Initial Hydrostatic 1928

(B) First Initial Flow 33

(C) First Final Flow 34

(D) Initial Shut-In 470

(E) Second Initial Flow 34

(F) Second Final Flow 35

(G) Final Shut-In 810

(H) Final Hydrostatic 1855

☒ Test 1125

☒ Jars 250

☒ Safety Joint 75

☐ Circ Sub

☐ Hourly Standby

☒ Mileage 100 RT x 2 = 250

☐ Sampler

☐ Straddle

☐ Shale Packer

☐ Extra Packer

☐ Extra Recorder

☐ Day Standby 800-

☐ Accessibility

Sub Total 2500

T-On Location 9:30

T-Started 10:30

T-Open 12:54

T-Pulled 15:00

T-Out 17:27

Comments Pick tool up at 3:00
on 1-8-11

☐ Ruined Shale Packer

☐ Ruined Packer

☐ Extra Copies

Sub Total 0

Total 2500-

MP/DST Disc't

Initial Open 15

Initial Shut-In 30

Final Flow 30

Final Shut-In 60

Approved By

Our Representative

TriLOBITE Testing Inc. shall not be liable for damaged of any kind of the property or personnel of the one for whom a test is made, or for any loss suffered or sustained, directly or indirectly, through the use of its equipment, or its statements or opinion concerning the results of any test, tools lost or damaged in the hole shall be paid for at cost by the party for whom the test is made.