



TRILOBITE TESTING INC.

P.O. Box 1733 • Hays, Kansas 67601

Test Ticket

NO. 38169 14191

Well Name & No. Sheryl Roberts 8-1 Test No. 1 Date 4-27-10
 Company H&C Elevation 2432 KB 2427 GL
 Address PO Box 86 Plainsville, KS 67663
 Co. Rep / Geo. Marc Downing Rig Am Eagle 3
 Location: Sec. 8 Twp. 7S Rge. 23W Co. Graham State K

Interval Tested 3742-3762 Zone Tested LKC 'D'
 Anchor Length 20 Drill Pipe Run 3740 Mud Wt. 8.9
 Top Packer Depth 3737 Drill Collars Run — Vis SI
 Bottom Packer Depth 3742 Wt. Pipe Run — WL 7.2
 Total Depth 3762 Chlorides 1000 ppm System LCM

Blow Description IFP - stg. sur blow throughout
ISI - no blow back
FFP - no blow 26 min - weak sur blow
FST - no blow back

Rec	Feet of	%gas	%oil	%water	%mud
1	mud w/o spts			100	

Rec Total 1 BHT 104 Gravity — API RW — @ — °F Chlorides — ppm

(A) Initial Hydrostatic 1820
 (B) First Initial Flow 12
 (C) First Final Flow 13
 (D) Initial Shut-In 17
 (E) Second Initial Flow 12
 (F) Second Final Flow 13
 (G) Final Shut-In 15
 (H) Final Hydrostatic 1808

☒ Test 1125
☐ Jars
☐ Safety Joint
☐ Circ Sub
☐ Hourly Standby
☒ Mileage 146 RT 182.50

T-On Location 100%
 T-Started 1046
 T-Open 1242
 T-Pulled 1442
 T-Out 1628

Comments

Initial Open 30
 Initial Shut-In 30
 Final Flow 30
 Final Shut-In 30

☐ Sampler
☐ Straddle
☐ Shale Packer
☐ Extra Packer
☐ Extra Recorder
☐ Day Standby
☐ Accessibility
 Sub Total 1307.50

☐ Ruined Shale Packer
☐ Ruined Packer
☐ Extra Copies
 Sub Total 0
 Total 1307.50

Approved By

Our Representative

Brian Farnbank (H&C)

Trilobite Testing Inc. shall not be liable for damaged of any kind of the property or personnel of the one for whom a test is made, or for any loss suffered or sustained, directly or indirectly, through the use of its equipment, or its statements or opinion concerning the results of any test, tools lost or damaged in the hole shall be paid for at cost by the party for whom the test is made.



TRILOBITE TESTING INC.

P.O. Box 1733 • Hays, Kansas 67601

Test Ticket

NO. 38170

RECEIVED
APR 29 2010

Well Name & No. Sheryl Roberts 8-1 Test No. 2/2 1/2 Date 4-28-10
 Company H+C Elevation 2432 KB 2427 GL
 Address _____
 Co. Rep / Geo. Marc Downing Rig Am Eagle 3
 Location: Sec. 8 Twp. 7S Rge. 23W Co. Graham State K

Interval Tested 3832-3866 Zone Tested LKC "J"
 Anchor Length 34 Drill Pipe Run 3834 Mud Wt. 9.1
 Top Packer Depth 3827 Drill Collars Run _____ Vis 52
 Bottom Packer Depth 3832 Wt. Pipe Run _____ WL 7.8
 Total Depth 3866 Chlorides 1900 ppm System LCM _____
 Blow Description IFP- weak blow throughout 1/4-1"
ISI- no blow back
FFP- weak blow throughout sur- 1/4"
FSI- no blow back

Rec <u>15</u>	Feet of <u>mud</u>	%gas	%oil	%water	<u>100</u> %mud
Rec _____	Feet of _____	%gas	%oil	%water	%mud
Rec _____	Feet of _____	%gas	%oil	%water	%mud
Rec _____	Feet of _____	%gas	%oil	%water	%mud
Rec _____	Feet of _____	%gas	%oil	%water	%mud

Rec Total 15 BHT 106 Gravity _____ API RW _____ @ _____ °F Chlorides _____ ppm

(A) Initial Hydrostatic 1886
 (B) First Initial Flow 14
 (C) First Final Flow 18
 (D) Initial Shut-In 1295
 (E) Second Initial Flow 18
 (F) Second Final Flow 21
 (G) Final Shut-In 1259
 (H) Final Hydrostatic 1871

☒ Test 1125
☐ Jars _____
☐ Safety Joint _____
☐ Circ Sub _____
☒ Hourly Standby 1 hr 100'
☒ Mileage X2 146 RT 438
☐ Sampler _____
☐ Straddle _____
☐ Shale Packer _____
☐ Extra Packer _____
☐ Extra Recorder _____
☐ Day Standby _____
☐ Accessibility _____
 Sub Total 1772.50

T-On Location 0639 1142
 T-Started 0639 1227
 T-Open 1356
 T-Pulled 1556
 T-Out 1733
 Comments 1st test did
not go - mix mud &
condition hole again
mileage to loss tool
☐ Ruined Shale Packer _____
☐ Ruined Packer _____
☐ Extra Copies _____
 Sub Total 0
 Total 1772.50

Initial Open 30
 Initial Shut-In 30
 Final Flow 30
 Final Shut-In 30

Approved By _____

Our Representative Brian Fennell (Hays)

Trilobite Testing Inc. shall not be liable for damaged of any kind of the property or personnel of the one for whom a test is made, or for any loss suffered or sustained, directly or indirectly, through the use of its equipment, or its statements or opinion concerning the results of any test, tools lost or damaged in the hole shall be paid for at cost by the party for whom the test is made.