15-163-03200-00-00

4-**041859**

12-4

API Number:15-    - 12-4-96

NW NW NW    /4 SEC.__29__, __08__ S, __17__ W
4950                    feet from S section line
4950                    feet from E section line

Operator license# **5285**

Lease:_____**Russ**_____ Well #___**1**___

Operator:___**Dane G. Hansen Trust**___

County:_____**Rooks**_____    108.94

Address:___**P.O. Box 187**___

Well total depth_____**3352**_____ feet

___**Logan, Kansas 67646**___

Conductor Pipe:__**0**__ inch @____**0**____ feet

Surface pipe 8 5/8 Inch @____**178**____feet
w/ 150 sxs.cmt.

Aband. oil well_**X**_, Gas well_____, Input well___, SWD___, D & A_____

Plugging contractor:____**Allied Cementing, Inc.**____    License#_____-_____

Address:____**Russell, Kansas 67665**____

Company to plug at: Hour:__**8:00 A.M.**__Day:_**4**_ Month:____**December**____ Year ____**1996**____

Plugging proposal received from:____**Richard L. Wallgren, Sr.**____

Company:___**Dane G. Hansen Trust**___    Phone:___**913-483-2627**___

Were:_**5 1/2" casing set at 3344' w/150 sxs.**_
**Perfs. at 3048' - 3244'. Salt at 2050' - Anhy. at 1265' - Dakota at 725' - W.L.M. 3200'**
**Ordered 300 sxs 60/40 pozmix - 10% gel with 1/4# F.C. plus 500# hulls.**

Plugging Proposal Received by:_**Dennis L. Hamel**___    12-13-96

Plugging operations attended by agent?  All[    ], Part[    ], None[ **X** ]

Completed:  Hour:**11:30 A.M.**,Day:_**4**_, Month:____**December**____, Year:**1996**

Actual plugging report:_**Pumped down 5 1/2" casing - 275 sxs 60/40 pozmix - 10% gel with 400#**
**hulls.  Max. P.S.I. 500#.  S.I.P. 200#.**
**8 5/8" S.P. - pumped 25 sxs 60/40 pozmix - 10% gel with 100# hulls.  Max. P.S.I. 400#.**
**S.I.P. 200#.**

Remarks:___**Allied Cementing.**___
**Condition of casing(in hole):**  GOOD_**X**_ BAD_____    **Anhy.plug:** YES__**X**__ NO_____
**Bottom plug(in place):** YES_**X**_, CALC_____, NO_____    **Dakota plug:** YES__**X**__, NO_____
**Plugged through** TUBING_____, CASING___**X**___.    **Elevation:**_____

I did[    ]/did not[ X ] observe the plugging.

_Dennis L. Hamel_
(agent)
Form CP-2/3