Notice: Fill out COMPLETELY and return to Conservation Division at the address below within 60 days from plugging date.

KANSAS CORPORATION COMMISSION
OIL & GAS CONSERVATION DIVISION
WELL PLUGGING RECORD
K.A.R. 82-3-117

Form CP-4
December 2003
Type or Print on this Form
Form must be Signed
All blanks must be Filled

Lease Operator: Gore Oil Company

Address: P.O. Box 2757, Wichita, KS 67201-2757

Phone: (316) 263 - 3535 Operator License #: 5552

Type of Well: Oil
(Oil, Gas D&A, SWD, ENHR, Water Supply Well, Cathodic, Other) Docket #: *(If SWD or ENHR)*

The plugging proposal was approved on: 3-8-06 *(Date)*

by: Herb Deines *(KCC District Agent's Name)*

Is ACO-1 filed? ☑ Yes ☐ No If not, is well log attached? ☐ Yes ☐ No

Producing Formation(s): List All *(If needed attach another sheet)*

Arbuckle Depth to Top: 3440' Bottom: 3443' T.D. 3443'

Depth to Top: Bottom: T.D.

Depth to Top: Bottom: T.D.

API Number: 15 - 163-01618-00-00

Lease Name: Rostocil

Well Number: C-4

Spot Location (QQQQ): SE - NW - NW -

4290 Feet from ☒ North / ☑ South Section Line

4290 Feet from ☑ East / ☒ West Section Line

Sec. 10 Twp. 9 S. R. 19 ☐ East ☑ West

County: Rooks

Date Well Completed: 9-15-50

Plugging Commenced: 3-8-06

Plugging Completed: 3-8-06

KCC 3-28-06 PKT Per operator Larry Jack.

Show depth and thickness of all water, oil and gas formations.

Oil, Gas or Water Records		*Casing Record (Surface Conductor & Production)*				
Formation	Content	From	To	Size	Put In	Pulled Out
Surface	Oil, Water	0'	310'	8 5/8"	310'	0'
Production	Oil, Water	0'	3440'	5 1/2"	3440'	0'

Describe in detail the manner in which the well is plugged, indicating where the mud fluid was placed and the method or methods used in introducing it into the hole. If cement or other plugs were used, state the character of same depth placed from (bottom), to (top) for each plug set.

Run tubing to 866' and stacked out. Hook up pump truck and wash down to 874' & hit solid bottom. Mix 25 sx cement, 13 bbls and pump down tubing. Pull 1 jt tubing to 837' to get back inside of good casing. Pump 75 sx cement, 41 bbls w/o hulls and circulate cement to surface. Pull tubing out of hole. Hook up to 5 1/2" casing and pump 50 sx cement w/o hulls until cement circulated out 8 5/8". Shut in 8 5/8" and squeeze in 10 sx down 5 1/2" pressured to 500# and held. Job complete.

Name of Plugging Contractor: Swift Services, Inc. License #: 32382

Address: P.O. Box 466, Ness City, KS 67560-0466

Name of Party Responsible for Plugging Fees: Gore Oil Company

State of Kansas County, Sedgwick, ss.

Larry M. Jack (Employee of Operator) or (Operator) on above-described well, being first duly sworn on oath, says: That I have knowledge of the facts statements, and matters herein contained, and the log of the above-described well is as filed, and the same are true and correct, so help me God.

RECEIVED
MAR 27 2006
KCC WICHITA

(Signature) Larry M Jack

(Address) Wichita, KS

STATE OF KANSAS NOTARY PUBLIC REBECCA K. CRAWFORD State of Kansas My Appt. Exp. 3-20-07

SUBSCRIBED and SWORN TO before me this 23rd day of March, 20 06

Rebecca K. Crawford Notary Public My Commission Expires: 3-20-07

Mail to: KCC - Conservation Division, 130 S. Market - Room 2078, Wichita, Kansas 67202

Pam