

CARD MUST BE TYPED

State of Kansas

CARD MUST BE SIGNED

AMENDED INTENTION TO DRILL**NOTICE OF INTENTION TO DRILL**

(see rules on reverse side)

Expected Spud Date.....Unknown  
month day year

API Number 15— 059-24,306

-00-00 ✓ ND

OPERATOR: License # 09098SE/4 SE/4 SE/4 Sec. 1 Twp. 18 S, Rg. 20 X EastName McConathy Production Co., Inc.330 Ft. from South Line of SectionAddress 509 Market St., Suite 200330 Ft. from East Line of SectionCity/State/Zip Shreveport, LA 71101

(Note: Locate well on Section Plat on reverse side)

Contact Person Terry W. BuckNearest lease or unit boundary line ..... 330 feetPhone 318/227-1498County FranklinCONTRACTOR: License # UnknownLease Name Hanson Well # 1

Name .....

Ground surface elevation 1038' feet MSL

City/State .....

Domestic well within 330 feet: yes X no

Well Drilled For: Well Class: Type Equipment:

Municipal well within one mile: yes X noOil Storage Infield Mud RotaryDepth to bottom of fresh water..... UnknownX Gas Inj. X Pool Ext. X Air RotaryDepth to bottom of usable water ..... 200OWWO Expl Wildcat CableSurface pipe by Alternate: 1 2 X

If OWWO: old well info as follows:

Surface pipe planned to be set ..... 21'

Operator .....

Conductor pipe required ..... None

Well Name .....

X Projected Total Depth ..... 1000' feet

Comp Date..... Old Total Depth.....

X Formation ..... Bartlesville

I certify that well will comply with K.S.A. 55-101, et seq., plus eventually plugging hole to KCC specifications.

Date 3/7/88 Signature of Operator or Agent Terry W. Buck Title President

For KCC Use:


Conductor Pipe Required ..... 2-16-88 feet; Minimum Surface Pipe Required ..... 20 feet per Alt. X (2)This Authorization Expires 8-16-88 Approved By Jeff 3-11-88\* WAS: P.T.D. 850' Fm. Squirrel, Cattleman

Must be filed with the K.C.C. five (5) days prior to commencing well  
This card void if drilling not started within six (6) months of date received by K.C.C.

**Important procedures to follow:**

1. Notify District office before setting surface casing.
2. Set surface casing by circulating cement to the top.
3. File completion forms ACO-1 with K.C.C. within 120 days of well spud date, following instructions on ACO-1, side 1, and including copies of wireline logs.
4. Notify District office 48 hours prior to old well workover or re-entry.
5. Prior to filing Intent, prepare a proposed plugging plan in case well is D & A, then obtain approval of plan when calling district office prior to setting surface pipe.
6. Submit plugging report (CP-4) to K.C.C. after plugging is completed.
7. Obtain an approved injection docket number before disposing of salt water.
8. Notify K.C.C. within 10 days when injection commences or terminates.
9. If an alternate 2 completion, cement in the production pipe from below any usable water to surface within 120 days of spud date.

**A Regular Section of Land  
1 Mile = 5,280 Ft.**



MAR 10 1988  
3-10-88  
CONSERVATION DIVISION  
Wichita, Kansas

State Corporation Commission of Kansas  
Conservation Division  
200 Colorado Derby Building  
Wichita, Kansas 67202-1212  
(316) 263-3238