15-163-03363-00-00

6 030876

4-29-87

TO:
STATE CORPORATION COMMISSION
CONSERVATION DIVISION - PLUGGING SECTION
200 COLORADO DERBY BUILDING
WICHITA, KANSAS 67202

API NUMBER 15- 5-6-47

_____, SEC. 21 , T 9 S, R 18 W/E

2970 feet from S section line

2970 feet from E section line

TECHNICIAN'S PLUGGING REPORT

Operator License # 4519

Lease Name A. Stahl Well # 1

County Rooks

116.94

Operator: Chevron U.S.A. Inc.
Name&
Address P.O. Box 12116

Oklahoma City, Ok 73157

Well Total Depth 3598 feet

Conductor Pipe: Size_____ feet _____

Surface Casing: Size 8 5/8 feet 1504

Abandoned Oil Well X Gas Well_____ Input Well_____ SWD Well_____ D&A_____

Other well as hereinafter indicated_____

Plugging Contractor Halliburton Services

License Number_____

Address Hays, Kansas

Company to plug at: Hour:_____ Day: 29 Month: 4 Year:19 87

Plugging proposal received from Tony

(company name) Chevron U.S.A. Inc. (phone)_____

were: Chevron Engineers would : set CIBP at 3300 spot 5 sk cmt on CIBP, circulate gel

water to surface, laydown tubing to base of Dakota displace 100' of cmt mix, across

Dakota, laydown tubing to 50' displace cmt. mix. to base of cellar, fill 8 5/8-5½ Annulus

with econolite and squeeze.

_____ Plugging Proposal Received by Carl Goodrow *Carl Goodrow*
(TECHNICIAN)

Plugging Operations attended by Agent?: All_____ Part X None_____

Operations Completed: Hour: 8:15PM Day: 29 Month: 4 Year:19 87

ACTUAL PLUGGING REPORT 8 5/8" set at 1504' with 600 sks 5½" set at 3579 with 100 sks.

top perf. at 3367' Plugged bottom with CIBP and 10 sks cement 3300' to 3100'

A hole in casing wouldn't allow gel water to surface so tubing was laid down to establish

depth of fluid and hole in casing. Hole was at 130' of surface, So 240 sk cmet mix were

pumped down annulus. 25 sk were pumped down 5½ csg. to 300 # PSI and closed in.

Plug complete.

RECEIVED
STATE CORPORATION COMMISSION
6-25-87
JUN 25 1987
CONSERVATION DIVISION
Wichita, Kansas

Remarks:_____

(If additional description is necessary, use BACK of this form.)

I did not observe this plugging.

Signed *Carl Goodrow*
(TECHNICIAN)

Carl Goodrow

FORM CP-2/3
Rev.01-84