

Notice: Fill out COMPLETELY
and return to Conservation Division
at the address below within
30 days from plugging date.

KANSAS CORPORATION COMMISSION
OIL & GAS CONSERVATION DIVISION
WELL PLUGGING RECORD
K.A.R. 82-3-117

Form CP-4
September 2003
Type or Print on this Form
Form must be Signed
All blanks must be Filled

Lease Operator: Resource Operations, Inc.
Address: P.O. Box 9487 Tulsa, OK. 74157
Phone: (918) 446 6114 Operator License #: 30364
Type of Well: Oil Docket #: _____
(Oil, Gas D&A, SWD, ENHR, Water Supply Well, Cathodic, Other) (If SWD or ENHR)
The plugging proposal was approved on: _____ (Date)
by: Virgil Clothier (KCC District Agent's Name)
Is ACO-1 filed? ☐ Yes ☐ No If not, is well log attached? ☐ Yes ☐ No
Producing Formation(s): List All (If needed attach another sheet)

Depth to Top: _____ Bottom: _____ T.D. _____
Depth to Top: _____ Bottom: _____ T.D. _____
Depth to Top: _____ Bottom: _____ T.D. _____

API Number: 15 - 159 - 02255 - 00 - 00
Lease Name: Tournear
Well Number: 2
Spot Location (OOQQ): _____ SW _____ SE _____ NE _____
2970 Feet from _____ North / ☒ South Section Line
990 Feet from ☒ East / _____ West Section Line
Sec. 29 Twp. 19 S. R. 9 _____ East ☒ West
County: Rice
Date Well Completed: 4-22-35
Plugging Commenced: 6-27-07
Plugging Completed: 6-28-07

Show depth and thickness of all water, oil and gas formations.

Oil, Gas or Water Records		Casing Record (Surface Conductor & Production)			
Formation	Content	From	To	Size	Pul In Pulled Out
				15-1/2"	161' None
				8-5/8"	3187' None

Describe in detail the manner in which the well is plugged, indicating where the mud fluid was placed and the method or methods used in introducing it into the hole. If cement or other plugs were used, state the character of same depth placed, from _____ feet to _____ feet each set.

Plugged off bottom with sand to 3100' and 8 sxs. cement. Perforated casing @1200', 800' and 250'. Ran tubing to 1200', pumped 75 sxs. cement, pulled tubing up to 800', pumped 75 sxs. cement, pulled up to 250', pumped 135 sxs. and circulated to surface. Ran 1" tubing down 15" surface to 250', pumped 50 sxs. cement & circulated to surface. Topped off with 25 sacks cement. Plugging Complete.

Name of Plugging Contractor: Mike's Testing & Salvage, Inc. License #: 31529
Address: P.O. Box 467 Chase, Kansas 67524

Name of Party Responsible for Plugging Fees: Resource Operations, Inc.

State of Kansas County: Rice ss.

Mike Kelso

(Employee of Operator) or (Operator) on above-described well, being first duly

sworn on oath, says: That I have knowledge of the facts statements, and matters herein contained, and the log of the above-described well is as filed, and the same are true and correct, so help me God.


(Signature) Mike Kelso

(Address) P.O. Box 467 Chase, Kansas 67524

SUBSCRIBED and SWORN TO before me this 6th day of July, 20 07

Irene Herzberg
Notary Public

My Commission Expires:



Mail to: KCC - Conservation Division, 130 S. Market - Room 2078, Wichita, Kansas 67202