



KANSAS CORPORATION COMMISSION
OIL & GAS CONSERVATION DIVISION

Form CDP-5
August 2008
Form must be Typed

EXPLORATION & PRODUCTION WASTE TRANSFER

Operator Name: <u>Stephen C. Jones</u>		License Number: <u>33453</u>
Operator Address: <u>12 North Armstrong Bixby, Ok. 74008</u>		
Contact Person: <u>Steve Jones</u>		Phone Number: (<u>918</u>) <u>366 - 3710</u>
Permit Number (API No. if applicable): <u>15031227390000</u>		Lease Name: <u>J. Birk</u>
Source of Waste: ☐ Emergency Pit ☐ Dike ☐ Workover Pit ☐ Settling Pit ☐ Burn Pit ☒ Drilling Pit ☐ Steel Pit ☐ Haul-off Pit ☐ ☐ Spill / Escape		Well Number: <u>7A</u> Source Location (QQQQ): <u>nw - sw - nw - nw</u> Sec. <u>28</u> Twp. <u>22s</u> R. <u>14</u> ☒ East ☐ West <u>990</u> Feet from ☒ North / ☐ South Line of Section <u>330</u> Feet from ☐ East / ☒ West Line of Section <u>Coffey</u> County
Type of waste to be disposed: ☒ Fluid ☐ Soil ☐ Mud / Cuttings ☐ Other: _____		
Amount of waste: _____ No. of loads <u>20</u> Barrels _____ Tons _____ YDS		
Destination of waste: ☐ Reserve Pit ☐ Haul Off Pit ☐ Disposal Well ☒ Lease Road ☐ Dike / Berm ☐ Other: _____		
If waste is transferred to another reserve pit, is the lease active? ☐ Yes ☐ No		
Location of waste disposal: _____		Date of Waste Transfer: <u>8-15-11</u>
Operator Name: <u>Stephen C. Jones</u>		License No.: <u>33453</u>
Lease Name: <u>J. BIRK</u>		Sec. <u>28</u> Twp. <u>22s</u> R. <u>14</u> ☒ East ☐ West
Docket No./API No.: <u>15031227390000</u>		County: <u>Coffey</u>
Comments: <u>No drilling mud was mixed. The drilling fluid was fresh water.</u>		

RECEIVED
NOV 14 2011
KCC WICHITA

The undersigned hereby certifies that he / she is <u>PRESIDENT</u>	
for <u>STEPHEN C. JONES</u> (Co.), a duly authorized agent, that all information shown hereon is true	
and correct to the best of his / her knowledge and belief.	
Subscribed and sworn to before me on this <u>10</u> day of <u>November</u> , <u>2011</u>	 Agent Signature
My Commission Expires <u>9-19-2014</u>	 Notary Public