15-077-20026-0001

2 040301

FEB 1 1 1987

To:
STATE CORPORATION COMMISSION
CONSERVATION DIVISION - PLUGGING SECTION
200 COLORADO DERBY BUILDING
WICHITA, KANSAS 67202

TECHNICIAN'S PLUGGING REPORT

API NUMBER 15-

SE NE, SEC. 16, T 35 S, R 6 E/W

3300 feet from S section line

1660 feet from E section line

Operator License # 9797

Lease Name Williams (Topaz) Well #

Operator: Selco Drlg. Inc.

County Harper 132.76

Name& Address P.O. Bx 7191
Moore Oklahoma
73153

Well Total Depth 4085 feet

Conductor Pipe: Size feet

Surface Casing: Size 10 3/4 feet 205

Abandoned Oil Well ____ Gas Well ____ Input Well ____ SWD Well X D&A ____

Other well as hereinafter indicated

Plugging Contractor Pool Well Service License Number 7874

Address Woodard Oklahoma.

Company to plug at: Hour: ____ Day: ____ Month: ____ Year: 19____

Plugging proposal received from Ron.

(company name) Pool Well Service (phone)

were:

Howard formation SWD Perfs 1870-1880 & 1938-1948
2 3/8 Disposal String 2100
4 1/2 4085

Plugging Proposal Received by Dist #2 Rice
(TECHNICIAN)

Plugging Operations attended by Agent?: All X Part ____ None ____

Operations Completed: Hour: 1640 Day: 11 Month: 2 Year: 19 87

ACTUAL PLUGGING REPORT The tubing was pulled from the well and a gauge ring was run from ground level to T.D. The casing was found to be sound, so a CIBP was run in and set at 3976'. The CIBP was then capped with 5 sacks of cement. The 4 1/2 was perforated at 255'. Halliburton then tied into the disposal string and pumped 40 sks of cement. The 4 1/2" casing was then tied into and 175 sks

Remarks: (If additional description is necessary, use BACK of this form.)

INVOICED

I (did), (did not) observe this plugging.

DATE 2-18-87

INV. NO. 16152

RECEIVED
STATE CORPORATION COMMISSION
FEB 17 1987 2-17-87
CONSERVATION DIVISION
Wichita, Kansas

Signed
(TECHNICIAN)

FORM CP-2/3
Rev. 01-84

of cement was pumped into the 4½ and up the backside
The cement did circulate.

Howco. 540483