

PRELIMINARY

For any interpretation, we've shall not, accept to the case of gross or wilful negligence or our part, be liable or responsible for any loss, costs, damages or expenses incurred or sustained by anyone resulting from any interpretation made by any of our officers, agents or employees. All interpretations are opinions based on inferences from electrical or other measurements and we cannot, but warrant the accuracy.

CONFIDENTIAL

Thank you for using Pioneer Energy Services
555-620-3909

Ogallah Kia, North to F Rd., 2 East to Cattle Guard,
Continue East on Rd. to shed

PIONEER
Subsea Energy Services

Port Collar @ 1755

Database File: sampler_shutlet_plat_2-31.db
Presentation Format: subsea
Dataset: 6/2/2026 05:28:57 (EDT) by Log SCH 111118
Created by: Depth in Feet scaled 1:240
Created by:

0 GR 150
0 CTEN (lb) 8000
1200 (case) 2FM

0 AMP (uV) 100.0 AMPREC 100.000 VOL 1200 Current Map
0 PIPTIME (mV) 20.0 AMPREC 100
0 CCL -0.5
AMPREC

1600
1650
1700
1750
1800
1850
1900
1950

Port Collar

0 GR 150
0 CTEN (lb) 8000
1200 (case) 2FM

0 AMP (uV) 100.0 AMPREC 100.000 VOL 1200 Current Map
0 PIPTIME (mV) 20.0 AMPREC 100
0 CCL -0.5
AMPREC

PIONEER
Subsea Energy Services

Main Pass

Database File: sampler_shutlet_plat_2-31.db
Presentation Format: subsea
Dataset: 6/2/2026 05:28:57 (EDT) by Log SCH 111118
Created by: Depth in Feet scaled 1:240
Created by:

0 GR 150
0 CTEN (lb) 8000
1200 (case) 2FM

0 AMP (uV) 100.0 AMPREC 100.000 VOL 1200 Current Map
0 PIPTIME (mV) 20.0 AMPREC 100
0 CCL -0.5
AMPREC

2750
2800
2850
2900
2950
3000
3050
3100
3150
3200
3250
3300
3350
3400
3450
3500
3550
3600
3650
3700
3750
3800
3850
3900
3950
4000
4050

Top of Sand
Base of Sand
Marker Joint 4450
Marker Joint 4500
Top of Sand
Base of Sand
Marker Joint 4550
Marker Joint 4600
Top of Sand
Base of Sand
Marker Joint 4650
Marker Joint 4700
Top of Sand
Base of Sand
Marker Joint