



Pioneer Energy Services

Dual Compensated Porosity Log

[illegible]

<<< Fold Here >>>

All interpretations are opinions based on inferences from electrical or other measurements and we cannot and do not guarantee the accuracy or correctness of any interpretation, and we shall not, except in the case of gross or willful negligence on our part, be liable or responsible for any loss, costs, damages, or expenses incurred or sustained by anyone resulting from any interpretation made by any of our officers, agents or employees. These interpretations are also subject to our general terms and conditions set out in our current Price Schedule.

Comments


Thank you for using Pioneer Energy Services
www.pioneerres.com
785 625 3858
Medicine Lodge,
South to Scott Canyon Rd, 2 1/2 East,
North into


Database File: c:\warrior\data\val_talbott #8-9\val_talbott_8-9hd.db
Dataset Pathname: dil\vastkml
Presentation Format: cdl
Dataset Creation: Sat May 31 13:43:32 2014
Charted by: Depth in Feet scaled 1:600


Charted by: Depth in Feet scaled 1:600

0	Gamma Ray	150
6	Caliper (GAPI)	16

30	Compensated Density		-10
2	Bulk Density		3
15000	Line Tension		0
2.625	DGA	3.425	-0.25
		Correction	0.25
LSPD			







Database File: c:\warrior\data\val_talbott #8-9\val_talbott_8-9hd.db
Dataset Pathname: dil\vastkml
Presentation Format: cndlspec
Dataset Creation: Sat May 31 13:43:32 2014
Charted by: Depth in Feet scaled 1:240

0	Gamma Ray	150	30	Compensated Neutron (Limestone)		-10
6	Caliper (GAPI)	16	30	Compensated Density (Limestone)		-10
			2.625	DGA	3.425	-0.25
			Correction		0.25	
			15000	Line Tension		0
						LSPD

