



10244 NE Hwy. 61
 P.O. Box 8613
 Pratt, Kansas 67124
 Phone 620-672-1201

FIELD SERVICE TICKET
 1718 02369 A

DATE _____ TICKET NO. _____

DATE OF JOB <u>08-12-10</u> DISTRICT <u>PRATT</u>		NEW WELL <input type="checkbox"/> OLD WELL <input checked="" type="checkbox"/> PROD <input type="checkbox"/> INJ <input type="checkbox"/> WDW <input type="checkbox"/> CUSTOMER ORDER NO.:				
CUSTOMER <u>BEREN CORP.</u>		LEASE <u>DEAN</u>		WELL NO. <u>5</u>		
ADDRESS		COUNTY <u>BARBER</u>		STATE <u>Ks</u>		
CITY		STATE		SERVICE CREW <u>Sullivan, mclison, whitman</u>		
AUTHORIZED BY		JOB TYPE: <u>CNW 5 1/2 ton steel</u>				
EQUIPMENT#	HRS	EQUIPMENT#	HRS	EQUIPMENT#	HRS	TRUCK CALLED <u>08-11-10</u> DATE <u>08-11-10</u> AM <u>1200</u> TIME
<u>33708-20920</u>	<u>40</u>	<u>mm</u>				ARRIVED AT JOB <u>08-11-10</u> AM <u>2200</u> PM
<u>19960-19918</u>	<u>40</u>	<u>mm</u>				START OPERATION <u>08-12-10</u> AM <u>0450</u> PM
<u>19867</u>						FINISH OPERATION AM <u>0530</u> PM
						RELEASED <u>08-12-10</u> AM <u>0615</u> PM
						MILES FROM STATION TO WELL <u>40</u>

CONTRACT CONDITIONS: (This contract must be signed before the job is commenced or merchandise is delivered).

The undersigned is authorized to execute this contract as an agent of the customer. As such, the undersigned agrees and acknowledges that this contract for services, materials, products, and/or supplies includes all of and only those terms and conditions appearing on the front and back of this document. No additional or substitute terms and/or conditions shall become a part of this contract without the written consent of an officer of Basic Energy Services LP.

SIGNED: [Signature]
 (WELL OWNER, OPERATOR, CONTRACTOR OR AGENT)

ITEM/PRICE REF. NO.	MATERIAL, EQUIPMENT AND SERVICES USED	UNIT	QUANTITY	UNIT PRICE	\$ AMOUNT
CP 105	AA-2 cmt	SK	220		3740 00
CP 103	60/40 doz cmt	SK	100		1,200 00
CC 200	Cmt gnt	lb	930		232 50
CC 102	coll pipe	lb	26		96 20
CC 201	oil service	lb	1,322		385 74
CC 111	salt	lb	1,113		556 50
CF 607	latch door plug & Barflo 5 1/2	SA	1		400 00
CF 1251	White fill shoe	SA	1		360 00
CF 1651	Turbolite	SA	12		1,320 00
CF 1901	BAF at	SA	1		290 00
E 101	Heavy Grit mix	mi	80		560 00
CE 240	Blacking - mixing charge	SK	320		448 00
E 113	Bulk Believing	TIN	596		937 60
CE 206	Drath charge 5001-6000	SA	1		2,890 00
CE 504	plug container Portel	SA	1		250 00
SC03	Shim Gulp	SA	1		175 00
E 100	pralya mix	mi	40		170 00
SUB TOTAL					

CHEMICAL / ACID DATA:			

SERVICE & EQUIPMENT	%TAX ON \$	
MATERIALS	%TAX ON \$	
TOTAL		<u>7,975 8</u>

DL5

SERVICE REPRESENTATIVE: [Signature] THE ABOVE MATERIAL AND SERVICE ORDERED BY CUSTOMER AND RECEIVED BY: [Signature]
 (WELL OWNER OPERATOR CONTRACTOR OR AGENT)

FIELD SERVICE ORDER NO. _____

no trespass arising from operations performed by BEA or its subsidiaries, agents, employees, independent contractors, licensees, franchisees, holders, or legal actions or proceedings, overriding royalty interest, or concerning the operations of BEA.



TREATMENT REPORT

Customer BERAN CORP. Lease No. _____ Date 08-12-10
 Lease DEAN Well # 5
 Field Order # 2349 Station PRATT Casing 5 1/2 Depth 5120' County BARBER State KS
 Type Job CNW 5 1/2 longstring Formation _____ Legal Description 35-33-11

PIPE DATA		PERFORATING DATA		FLUID USED		TREATMENT RESUME		
Casing Size	Tubing Size	Shots/Ft		Acid	RATE	PRESS	ISIP	
<u>5 1/2</u>							5 Min.	
Depth <u>3080</u>	Depth	From	To	Pre Pad	Max		10 Min.	
Volume <u>120</u>	Volume	From	To	Pad	Min		15 Min.	
Max Press <u>2000</u>	Max Press	From	To	Frac	Avg		Annulus Pressure	
Well Connection <u>P.C.</u>	Annulus Vol.	From	To		HHP Used		Total Load	
Plug Depth <u>3080</u>	Packer Depth	From	To	Flush	Gas Volume			

Customer Representative _____ Station Manager DAVE SCOTT Treater Robert Johnson

Service Units	<u>19867</u>	<u>33709</u>	<u>20920</u>	<u>19960</u>	<u>19718</u>				
Driver Names	<u>Sullivan</u>	<u>Molson</u>		<u>Whittan</u>					

Time	Casing Pressure	Tubing Pressure	Bbls. Pumped	Rate	Service Log
<u>2200</u>					<u>ON LOC S-4, 120 STS</u>
					<u>RUN 120 STS 5 1/2 # 15.5 CSP,</u>
					<u>cont. 1, 3, 5, 7, 9, 11, 13, 15, 17, 19, 21, 23</u>
					<u>skipped # 12</u>
<u>0410</u>					<u>CASING and Bottom)</u>
<u>0420</u>					<u>Hook Up, circ.</u>
<u>0440</u>	<u>300</u>		<u>5</u>	<u>4</u>	<u>1st Spacer</u>
			<u>20</u>	<u>5.5</u>	<u>mix SCALLOPPAD 50 sk GOLF 1002</u>
	<u>300</u>		<u>50</u>		<u>mix AA-2 cont 220 sk</u>
					<u>Shut down cont mix dr. WASH, pump, Lin</u>
					<u>Polysac Plug</u>
<u>0512</u>				<u>6</u>	<u>1st Disp</u>
	<u>300</u>		<u>72</u>		<u>Lift Psi</u>
	<u>800</u>		<u>100</u>	<u>4</u>	<u>Slow Rates</u>
<u>0530</u>	<u>2,000</u>		<u>120</u>		<u>Plug down</u>
			<u>4</u>	<u>3</u>	<u>shut M.H. w/ 20 sk GOLF 1002</u>
			<u>6</u>		<u>shut M.H. w/ 30 sk GOLF 1002</u>
					<u>SOB Complete</u>
					<u>Thank you!</u>