



CONSOLIDATED
Oil Well Services, LLC



ENTERED

TICKET NUMBER 28970
LOCATION Eureka
FOREMAN Kevin McCoy

PO Box 884, Chanute, KS 66720
620-431-9210 or 800-467-8676

FIELD TICKET & TREATMENT REPORT
CEMENT

DATE	CUSTOMER #	WELL NAME & NUMBER	SECTION	TOWNSHIP	RANGE	COUNTY
7-29-10	7865	Beachner #5-4				Labeite
CUSTOMER						
SEK Energy LLC				Co.		
MAILING ADDRESS						
P.O. Box 55				Tools	TRUCK #	DRIVER
CITY		STATE	ZIP CODE		TRUCK #	DRIVER
Benedict		Ks	66714		445	John S.
					515	Chris

JOB TYPE Longstring 0 HOLE SIZE 6 3/4" HOLE DEPTH 837' CASING SIZE & WEIGHT 4 1/2 10.5# new
 CASING DEPTH 830' DRILL PIPE _____ TUBING _____ OTHER _____
 SLURRY WEIGHT 13.4* SLURRY VOL 28 BBL WATER gal/sk 9.0 CEMENT LEFT in CASING 0'
 DISPLACEMENT 13.2 BBL DISPLACEMENT PSI 450 PSI 700 Bump Plug RATE _____

REMARKS: Safety Meeting: Rig up to 4 1/2 casing. Break Circulation w/ 15 BBL fresh water.
Pump 4 sks Gel Flush w/ Hulls, 5 BBL Dye water. Mixed 95 sks Thick Set Cement w/ 1/4"
Fluocel /sk @ 13.4*/gal, yield 1.65. wash out Pump & Lines. shut down. Release Plug. Displace
w/ 13.2 BBL fresh water. FINAL Pumping Pressure 450 psi. Bump Plug to 700 psi. wait 2
Minutes. Release Pressure. float held. Shut casing in @ 0 psi. Good Cement Returns to
SURFACE = 6 BBL slurry to Pit. Job Complete. Rig down.

ACCOUNT CODE	QUANTITY or UNITS	DESCRIPTION of SERVICES or PRODUCT	UNIT PRICE	TOTAL
5401	1	PUMP CHARGE	925.00	925.00
5406	60	MILEAGE 15 well of 2	3.65	219.00
1126 A	95 sks	THICK Set Cement	17.00	1615.00
1107	25 #	Fluocel 1/4" /sk	2.10	52.50
1118 A	200 #	Gel Flush	.20	40.00
1105	50 #	Hulls	.39	19.50
5407 A	5.22 Tons	60 miles Buck Delv.	1.20	375.84
4404	1	4 1/2 Top Rubber Plug	45.00	45.00
			Sub Total	3291.84
			SALES TAX 7.55%	133.78
			ESTIMATED TOTAL	3425.62

Revin 3737

AUTHORIZATION witnessed By Doug Lamb

TITLE President

DATE 7-29-10

I acknowledge that the payment terms, unless specifically amended in writing on the front of the form or in the customer's account records, at our office, and conditions of service on the back of this form are in effect for services identified on this form.