Form CP-111 March 2009 Form must be Typed Form must be signed

## TEMPORARY ABANDONMENT WELL APPLICATION

All blanks must be complete

Phone 316.630.4000

Phone 620.432.2300

Phone 785.625.0550

Phone 316.734.4933

OPERATOR: License#	API No. 15									
Name:										
Address 1:					Sec					
Address 2:				feet from						
City:						fe	et from $\Box$ E	/ $\square$ W Li	ine of Section	
Contact Person:				GPS Location: Lat:, Long:, (e.g. xx.xxxxx)						
Phone:( )				County: Well #:						
Contact Person Email:				Elevation: GL KB						
Field Contact Person:					check one) 🗌 O			_		
				SWD Permit #: ENHR Permit #:						
Field Contact Person Phone: ( )				Gas Storage Permit #:						
				Spud Date:		Da	te Shut-In:			
	Conductor	Surface	Pr	oduction	Intermediat	е	Liner	Tu	ubing	
Size										
Setting Depth										
Amount of Cement										
Top of Cement										
Bottom of Cement										
Depth and Type:	ALT. II Depth o	f: DV Tool:(depth)	w /	Set at:	s of cement P	ort Collar:(			ack of cement	
Geological Data:										
Formation Name	Formation	Top Formation Base			Compl	etion Information	n			
		to Fee	t Perfe	oration Interval	to			l to	Feet	
2	At:	to Feet			to					
		Submitt	ted Ele	ectronicall	y					
Do NOT Write in This Date Tested: Results:			esults:	Date Plugged: Date Repaired: Date Put Back in Service:						
Space - KCC USE ONLY										
Review Completed by: Comm				nents: TA Approved: Yes Denied					Denied	
		Mail to the App	propriate	KCC Conserv	ration Office:					
KCC District Office #1 - 210 E. Frontview, Suite A, Dodge City, KS 67801								Phone 620.225.8888		

KCC District Office #2 - 3450 N. Rock Road, Building 600, Suite 601, Wichita, KS 67226

Underground Porosity Gas Storage (UPGS) 8200 E. 34th Street Circle N., Suite 1003, Wichita, KS 67226

KCC District Office #3 - 1500 SW Seventh Steet, Chanute, KS 66720

KCC District Office #4 - 2301 E. 13th Street, Hays, KS 67601-2651

Bruce Oil Company Bachofer 27 jts. 864 ft.

ECHOMETER COMPANY 5001 DITTO LANE, WICHITA FALLS, TEXAS 76302

