

KANSAS CORPORATION COMMISSION OIL & GAS CONSERVATION DIVISION 1050204

Form CDP-1 May 2010 Form must be Typed

APPLICATION FOR SURFACE PIT

Submit in Duplicate							
Operator Name:		License Number:					
Operator Address:							
Contact Person:			Phone Number:				
Lease Name & Well No.:			Pit Location (QQQQ):				
Depth fro	Artificial Liner? Yes No Length (feet)						
material, thickness and installation procedure. Distance to nearest water well within one-mile ofeet Depth of water well Emergency, Settling and Burn Pits ONLY:	Depth to shallor Source of inforr		feet. electric log KDWR				
Producing Formation:	Type of material utilized in drilling/workover:						
Number of producing wells on lease:	Number of working pits to be utilized:						
Barrels of fluid produced daily:	Abandonment procedure:						
Does the slope from the tank battery allow all s flow into the pit?Yes No	Drill pits must be closed within 365 days of spud date.						
Submitted Electronically		· · · · ·					

		KCC OFFICE USE ONLY	Liner	Steel Pit RFAC RFAS
Date Received:	Permit Number:	Permit Date:		Lease Inspection: Yes No

Mail to: KCC - Conservation Division, 130 S. Market - Room 2078, Wichita, Kansas 67202

Conservation Division Finney State Office Building 130 S. Market, Rm. 2078 Wichita, KS 67202-3802

Thomas E. Wright, Chairman Ward Loyd, Commissioner



phone: 316-337-6200 fax: 316-337-6211 http://kcc.ks.gov/

Corporation Commission

Sam Brownback, Governor

February 02, 2011

LeRoy Holt II Russell Oil, Inc. PO BOX 8050 EDMOND, OK 73083

Re: Drilling Pit Application Lawrence 3-D Sec.36-17S-13W Barton County, Kansas

Dear LeRoy Holt II:

District staff has inspected the location and has determined that an unsealed condition will present a pollution threat to water resources.

District staff has recommended that the Workover pit be lined. If a plastic liner is to be used it must have a minimum thickness of 10 mil. Integrity of the liner must be maintained at all times.

NO completion fluids or non-exempt wastes shall be placed in the Workover pit.

The free fluids in the Workover pit should be removed as soon as practical after drilling operations have ceased. The fluids should be taken to an authorized disposal well. Please call the District Office at (785) 625-0550 when the fluids have been removed. Please file form CDP-5 (August 2008), Exploration and Production Waste Transfer, through KOLAR within 30 days of fluid removal.

If you have any questions or concerns please feel free to contact the District Office at (785) 625-0550.