



sh. brn silt, grys silt siltstone	sh. brn silt, grys silt siltstone	sh. gry, brn	sh. gry, brn	sh. gry, brn	sh. gry, brn	sh. brn silt, grys silt siltstone	sh. brn silt, grys silt siltstone
LS: wh. to f. ch. oil w/ fass. incl. PP, PP, Lt. silt, p. str. PP, f. g. on crushing No odor & w. l. t. n	LS: wh. to f. ch. oil w/ fass. incl. PP, PP, Lt. silt, p. str. PP, f. g. on crushing No odor & w. l. t. n	LS: wh. to f. ch. oil w/ fass. incl. PP, PP, Lt. silt, p. str. PP, f. g. on crushing No odor & w. l. t. n	LS: wh. to f. ch. oil w/ fass. incl. PP, PP, Lt. silt, p. str. PP, f. g. on crushing No odor & w. l. t. n	LS: wh. to f. ch. oil w/ fass. incl. PP, PP, Lt. silt, p. str. PP, f. g. on crushing No odor & w. l. t. n	LS: wh. to f. ch. oil w/ fass. incl. PP, PP, Lt. silt, p. str. PP, f. g. on crushing No odor & w. l. t. n	LS: wh. to f. ch. oil w/ fass. incl. PP, PP, Lt. silt, p. str. PP, f. g. on crushing No odor & w. l. t. n	LS: wh. to f. ch. oil w/ fass. incl. PP, PP, Lt. silt, p. str. PP, f. g. on crushing No odor & w. l. t. n

Recovery: 10' mud  
HYD: 1792-1707#  
FP: 13-18#  
BHP: 833#  
BH Temp: 95°F

DST #2 3518'-3535'  
30-30-0-0  
IF: wk blow died in 1 min.  
Recovery: 1' mud  
Oil Spots in tool  
HYD: 1779-1724#  
FP: 11-11#  
BHP: 37#  
BH Temp: 91°F

DST #3 3543'-3564'  
30-30-0-0  
IF: wk blow died in 8 min.  
Recovery: 5' Mud  
sli. Oil Show  
HYD: 1810-1753#  
FP: 11-15#  
BHP: 1186#

DST #4 3564'-3577'  
30-30-0-0  
Wk. blow died in 20 min.  
Recovery: 5' Mud  
HYD: 1775-1758#  
FP: 10-18#  
BHP: 1029#  
BH Temp: 90°F