



WILLIS WELL SERVICE

P.O. BOX 474
CHANUTE, KS 66720
620-431-4444
620-431-8583

5105

DD

DATE: March 28 EQUIP. USED: Murray Rig

COMPANY NAME: Celt Energy

LEASE NAME: Clines F-2

STARTING TIME: 8⁰⁰ ENDING TIME: 5

REMARKS: We drove to location set up
2 3/8 run drill collar in w/ bit in and
2 3/8 upset in set to drill. We drill
rubber plug, cement ^{byble} shoe 3' cement
show we drill 13' feet stop waited 30min
no fluid started up drilling one more feet
show oil stop waited 30 min blow oil out
Pulled up 25' overmix 122000205 103500
122000230-2500.00

PARTS: Compressor 150⁰⁰ x 9 = 1350⁰⁰
stripper rubber / Head 200⁰⁰ Power swivel 50⁰⁰ x 9 = 450
drill collars rental 100⁰⁰ 3 3/8 bit 400⁰⁰

NUMBER OF HOURS: 9 COST/HR.: 115⁰⁰
PARTS COST: 2500⁰⁰ TOTAL COST: 1035⁰⁰ 3535⁰⁰

OPER. ED AUTHORIZED SIGNATURE _____



WILLIS WELL SERVICE

P.O. BOX 474
CHANUTE, KS 66720
620-431-4444
620-431-8583

5106

DATE: March 29 EQUIP. USED: Missouri Rig

COMPANY NAME: Colt Energy

LEASE NAME: Clino F-2

STARTING TIME: 8⁰⁰ ENDING TIME: ~~6~~ 4³⁰

REMARKS: We drove to lease ~~run~~ pipe
in 6' fill-up we blow it out cleanup
well trap out ^{TD} 886' We re-tally 2 3/8 runs
it in set it ~~pickup~~ 3/4 rod at yard
run it in space out rig down

122000205 977.50
122000230 450.00
122000306 120.08

PARTS: Pipe dope 10'

1-8' x 3/4 pony rod w/ box 110.08

Compressor 150X 3 min = 430'

NUMBER OF HOURS: 8.5 COST/HR.: 115⁰⁰

PARTS COST: 570.08 TOTAL COST: 977.5
1547.58

OPER. SD AUTHORIZED SIGNATURE _____