

Kansas Corporation Commission Oil & Gas Conservation Division

1059613

Form CP-1
March 2010
This Form must be Typed
Form must be Signed
All blanks must be Filled

WELL PLUGGING APPLICATION

Form KSONA-1, Certification of Compliance with the Kansas Surface Owner Notification Act, MUST be submitted with this form.

OPERATOR: License #:		API No. 1	5				
Name:			If pre 1967, supply original completion date:				
Address 1:	Spot Des	Spot Description:					
Address 2:	_	· Sec Twp	o S. R	East West			
City: State:		_	Feet from	North / South	Line of Section		
Contact Person:			Feet from	East / West	Line of Section		
Phone: ()		Footages	Calculated from Neares		er:		
Filone. ()				SE SW			
			ame:				
		Lease IVe	arrie.	vveπ π			
Check One: Oil Well Gas Well OG	D&A Car	thodic Wate	r Supply Well Ot	her:			
SWD Permit #:	ENHR Permit #:		Gas Storage	Permit #:			
Conductor Casing Size:	Set at:		Cemented with:		Sacks		
Surface Casing Size:	_ Set at:		Cemented with:		Sacks		
Production Casing Size:	_ Set at:		Cemented with:		Sacks		
Elevation: (G.L. / K.B.) T.D.: Condition of Well: Good Poor Junk in Hole Proposed Method of Plugging (attach a separate page if adding Is Well Log attached to this application? Yes No. 1f ACO-1 not filed, explain why:	Casing Leak at:			ione Corral Formation)			
Plugging of this Well will be done in accordance with K. Company Representative authorized to supervise plugging							
Address:	(City:	State:	Zip:	-+		
Phone: ()							
Plugging Contractor License #:		Name:					
Address 1:	A	Address 2:					
City:			State:	Zip:	_+		
Phone: ()							
Proposed Date of Plugging (if known):							

Payment of the Plugging Fee (K.A.R. 82-3-118) will be guaranteed by Operator or Agent

Submitted Electronically



Kansas Corporation Commission Oil & Gas Conservation Division

1059613

Form KSONA-1
July 2010
Form Must Be Typed
Form must be Signed
All blanks must be Filled

CERTIFICATION OF COMPLIANCE WITH THE KANSAS SURFACE OWNER NOTIFICATION ACT

This form must be submitted with all Forms C-1 (Notice of Intent to Drill); CB-1 (Cathodic Protection Borehole Intent); T-1 (Request for Change of Operator Transfer of Injection or Surface Pit Permit); and CP-1 (Well Plugging Application).

Any such form submitted without an accompanying Form KSONA-1 will be returned.

Select the corresponding form being filed: C-1 (Intent) CB-1 (CB-1)	Cathodic Protection Borehole Intent) T-1 (Transfer) CP-1 (Plugging Application)
OPERATOR: License #	Well Location:
Name:	
Address 1:	County:
Address 2:	Lease Name: Well #:
City:	If filing a Form T-1 for multiple wells on a lease, enter the legal description of
Contact Person:	the lease below:
Phone: () Fax: ()	
Email Address:	
Surface Owner Information:	
Name:	When filing a Form T-1 involving multiple surface owners, attach an additional
Address 1:	sheet listing all of the information to the left for each surface owner. Surface owner information can be found in the records of the register of deeds for the
Address 2:	county, and in the real estate property tax records of the county treasurer.
City:	
the KCC with a plat showing the predicted locations of lease roads, tank	dic Protection Borehole Intent), you must supply the surface owners and a batteries, pipelines, and electrical lines. The locations shown on the plat in the Form C-1 plat, Form CB-1 plat, or a separate plat may be submitted.
☐ I certify that, pursuant to the Kansas Surface Owner Notice A owner(s) of the land upon which the subject well is or will be to CP-1 that I am filing in connection with this form; 2) if the form to form; and 3) my operator name, address, phone number, fax, at ☐ I have not provided this information to the surface owner(s). I at KCC will be required to send this information to the surface owner(s).	cknowledge that, because I have not provided this information, the vner(s). To mitigate the additional cost of the KCC performing this
task, I acknowledge that I am being charged a \$30.00 handling If choosing the second option, submit payment of the \$30.00 handling form and the associated Form C-1, Form CB-1, Form T-1, or Form CP-	fee with this form. If the fee is not received with this form, the KSONA-1
Submitted Electronically	

Form	CP1 - Well Plugging Application			
Operator	BP America Production Company			
Well Name	LOHMAN 1			
Doc ID	1059613			

Perforations And Bridge Plug Sets

Perforation Top	Perforation Base	Formation	Bridge Plug Depth
2624	2654	Herrington-Krider	2624
2678	2698	Winfield	



BP America Production Company

Lohman GU 1

Plug and Abandon

Field: Hugoton

Kearny County, Kansas

Section: 12 Township: 23S Range: 38W

Latitude: 38.064202° N Longitude: -101.444954° W

API #: 15-093-00191-00

DATE: June 22, 2011

Contacts								
Name	Title	Office	Cell	Email				
Talento, Lindsey	Well Intervention Engineer	281-366-6848	281-630-5186	lindsey.talento@bp.com				
McKamie, Jim	Sr Well Intervention Engineer	281-366-5401	281-660-4946	jim.mckamie@bp.com				
Cadena, Javier	Well Intervention Engineering TL	281-366-6505	281-210-7319	javier.cadena@bp.com				
Phelps, Jason	Well Intervention Superintendent	620-356-6961	620-353-4970	jason.phelps@bp.com				
Sonnefeld, Alan	Well Intervention Operations TL	281-366-0298	713-301-0506	alan.sonnefeld@bp.com				

Policy Reminder: Any changes to the written procedure requires an MOC. MOC (except BoD/SoR) approvals during execution have been delegated to the OTL.

Version 1 Rev Date: 6/22/2011 Page: 1 of 5

Intervention Objective

- Well has a stuck pump and economics do not justify the repair P&A well
- o Plug and abandon the well fulfilling the requirements of BP and the local government

Operational Information

- LCO location
- o H2S 5 ppm

Production & Expected Pressures

- o Well currently SI waiting on P&A
- Wellhead pressures: FTP/FCP 10 psig; SITP/SICP 75 psig; BHP 100 psi
- Highest Anticipated Surface Pressure 75 psi

Wellbore Information

Dimensions and Strengths

Size	Grade	Weight (lb/ft)	ID (in)	Drift (in)	Collapse (psi)	Internal Yield (psi)	Joint Yiel (k lbs)
**8-5/8"		29	8.017	7.892	1640	2470	
5-1/2"		14	5.012	4.887	3120	4270	172
2-3/8"	J-55	4.7	1.995	1.901	11780	11200	104.3

^{** 8-5/8&}quot;, 28#, H-40

Capacities

Size	Grade	Weight (lb/ft)	bbl/ft	ft/bbl	gal/ft	ft/gal
**8-5/8"	_	29	0.0624	16.0165	2.6223	0.3813
5-1/2"		14	0.0244	40.9796	1.0249	0.9757
2-3/8"	J-55	4.7	0.0039	258.645	0.1624	6.1582

^{** 8-5/8&}quot;, 28#, H-40


Lohman GU 1 - Plug and Abandon						
Version 1	Rev Date: 6/22/2011	Page: 3 of 5				

General Scope of Work

- 1. Notify KCC 5 days prior to commencing P&A operations
- 2. Pull Rods and Tubing
- 3. Set CIBP above top perforations
 - a. Top perf at 2624' md
- 4. Fill casing and run CBL
 - a. Determine TOC
 - b. Agree plan forward with KCC according to results of bond log
- 5. Lay in cement from CIBP to ~1000' md
- 6. Wait for cement to set
- 7. If cement behind 5-1/2" casing meets isolation requirements, fill 5-1/2" casing to surface
- 8. If required, punch holes in 5-1/2" casing and circulate cement
 - a. Fill 8-5/8" x 5-1/2" annulus and 5-1/2" casing to surface
- 9. Cut and cap casing 5' below ground level
- 10. Remove surface equipment and restore location


Version 1 Rev Date: 6/22/2011 Page: 2 of 5

Current WBD



Version 1 Rev Date: 6/22/2011 Page: 4 of 5

Proposed WBD



			L but he	
			- Arms	
			11 1 2 37	
			1.00	
			1.13	
		700		
			12.7	
			200	
		and the		
			12.	
			2.7	
			100	
			1 1 1	



BP America Production Company

Lohman GU 1

Plug and Abandon

Field: Hugoton

Kearny County, Kansas

Section: 12 Township: 23S Range: 38W

Latitude: 38.064202° N Longitude: -101.444954° W

API #: 15-093-00191-00

DATE: June 22, 2011

Contacts								
Name	Title	Office	Cell	Email				
Talento, Lindsey	Well Intervention Engineer	281-366-6848	281-630-5186	lindsey.talento@bp.com				
McKamie, Jim	Sr Well Intervention Engineer	281-366-5401	281-660-4946	jim.mckamie@bp.com				
Cadena, Javier	Well Intervention Engineering TL	281-366-6505	281-210-7319	javier.cadena@bp.com				
Phelps, Jason	Well Intervention Superintendent	620-356-6961	620-353-4970	jason.phelps@bp.com				
Sonnefeld, Alan	Well Intervention Operations TL	281-366-0298	713-301-0506	alan.sonnefeld@bp.com				

Policy Reminder: Any changes to the written procedure requires an MOC. MOC (except BoD/SoR) approvals during execution have been delegated to the OTL.

Version 1 Rev Date: 6/22/2011 Page: 1 of 5

Intervention Objective

- Well has a stuck pump and economics do not justify the repair P&A well
- o Plug and abandon the well fulfilling the requirements of BP and the local government

Operational Information

- LCO location
- o H2S 5 ppm

Production & Expected Pressures

- o Well currently SI waiting on P&A
- Wellhead pressures: FTP/FCP 10 psig; SITP/SICP 75 psig; BHP 100 psi
- Highest Anticipated Surface Pressure 75 psi

Wellbore Information

Dimensions and Strengths

Size	Grade	Weight (lb/ft)	ID (in)	Drift (in)	Collapse (psi)	Internal Yield (psi)	Joint Yiel (k lbs)
**8-5/8"		29	8.017	7.892	1640	2470	
5-1/2"		14	5.012	4.887	3120	4270	172
2-3/8"	J-55	4.7	1.995	1.901	11780	11200	104.3

^{** 8-5/8&}quot;, 28#, H-40

Capacities

Size	Grade	Weight (lb/ft)	bbl/ft	ft/bbl	gal/ft	ft/gal
**8-5/8"	_	29	0.0624	16.0165	2.6223	0.3813
5-1/2"		14	0.0244	40.9796	1.0249	0.9757
2-3/8"	J-55	4.7	0.0039	258.645	0.1624	6.1582

^{** 8-5/8&}quot;, 28#, H-40


Lohman GU 1 - Plug and Abandon						
Version 1	Rev Date: 6/22/2011	Page: 3 of 5				

General Scope of Work

- 1. Notify KCC 5 days prior to commencing P&A operations
- 2. Pull Rods and Tubing
- 3. Set CIBP above top perforations
 - a. Top perf at 2624' md
- 4. Fill casing and run CBL
 - a. Determine TOC
 - b. Agree plan forward with KCC according to results of bond log
- 5. Lay in cement from CIBP to ~1000' md
- 6. Wait for cement to set
- 7. If cement behind 5-1/2" casing meets isolation requirements, fill 5-1/2" casing to surface
- 8. If required, punch holes in 5-1/2" casing and circulate cement
 - a. Fill 8-5/8" x 5-1/2" annulus and 5-1/2" casing to surface
- 9. Cut and cap casing 5' below ground level
- 10. Remove surface equipment and restore location


Version 1 Rev Date: 6/22/2011 Page: 2 of 5

Current WBD



Version 1 Rev Date: 6/22/2011 Page: 4 of 5

Proposed WBD



			L but he	
			- Arms	
			11 1 2 37	
			1.00	
			1,13	
		700		
			12.7	
			200	
		and the	19-11	
			12.1	
			2.7	
			7.15	
			1 1 1	

Conservation Division Finney State Office Building 130 S. Market, Rm. 2078 Wichita, KS 67202-3802



Phone: 316-337-6200 Fax: 316-337-6211 http://kcc.ks.gov/

Sam Brownback, Governor

Mark Sievers, Chairman Ward Loyd, Commissioner Thomas E. Wright, Commissioner

August 02, 2011

DeAnn Smyers BP America Production Company 2225 W OKLAHOMA AVE ULYSSES, KS 67880-8416

Re: Plugging Application API 15-093-00191-00-00 LOHMAN 1 SW/4 Sec.12-23S-38W Kearny County, Kansas

Dear DeAnn Smyers:

This letter is to notify you that the Conservation Division has received your plugging proposal, form CP-1, for the above well and has reviewed the proposal for completeness. The central office will now forward your CP-1 to the district office listed below for review of the proposed plugging method. Please contact the district office for approval of your proposed plugging method at least five (5) days before plugging the well, pursuant to K.A.R. 82-3-113(b). If a workover pit will be used during the plugging of the well it must be permitted. A CDP-1 form must be filed and approved prior to the use of the pit in accordance with K.A.R. 82-3-600.

The Conservation Division's review of form CP-1, either in the central or district office, does not include an inquiry into well ownership or the filing operator's legal right to plug the well. This notice in no way constitutes authorization to plug the above well by persons not having legal rights of ownership or interest in the well.

This notice is void after January 29, 2012. The CP-1 filing does not bring the above well into compliance with K.A.R 82-3-111 with regard to the Commission's temporary abandonment requirements.

Sincerely, Production Department Supervisor

cc: District 1

(620) 225-8888