


RADIATION INTENSITY INCREASES

RESISTIVITY
Ohm-m


100
100
10
1.0
.2

2"=100
LR
SURF



RADIATION INTENSITY INCREASES

110
10





0600


0700

0800



0900



1000


1100



Gamma Ray







2500

2600


2700


2800

2900

3000

3100





3100

3200


3300


3400

3500

3600

3700





3800


3900


4000

4100

4200

4300





4400

4500


4600

4700



4800

4900



5000



Gamma Ray ↑



GAMMA RAY
API UNITS



NEUTRON
API UNITS

4700

4800

4900

5000

DEPTH

Company THE MAURICE L. BROWN COMPANY Drillers T.D. 5093

W. H. SOUTHERN MANUFACTURING CO. 50