



BASIC
ENERGY SERVICES
PRESSURE PUMPING & WIRELINE

10244 NE Hwy. 61
P.O. Box 8613
Pratt, Kansas 67124
Phone 620-672-1201

FIELD SERVICE TICKET
1718 05117 A

21-225-14W

DATE _____ TICKET NO. _____

DATE OF JOB 10-21-11		DISTRICT Pratt, Kansas		NEW WELL <input checked="" type="checkbox"/> OLD WELL <input type="checkbox"/>		PROD <input type="checkbox"/> INJ <input type="checkbox"/> WDW <input type="checkbox"/>		CUSTOMER ORDER NO.:	
CUSTOMER F.G. Holl Company, LLC.				LEASE Neeland Trust				WELL NO. 1-21	
ADDRESS				COUNTY Stafford		STATE Kansas			
CITY		STATE		SERVICE CREW C. Messick, T. Gibson, S. Young					
AUTHORIZED BY				JOB TYPE C.N.W. - Plug To Abandon					
EQUIPMENT#	HRS	EQUIPMENT#	HRS	EQUIPMENT#	HRS	TRUCK CALLED	DATE	AM	TIME
37216	3.5						10-21-11	PM	1:00
						ARRIVED AT JOB		AM	3:30
						START OPERATION		AM	5:00
33,708-20920	3.5					FINISH OPERATION		AM	8:30
						RELEASED	10-21-11	AM	9:00
19,831-19,862	3.5					MILES FROM STATION TO WELL			45

CONTRACT CONDITIONS: (This contract must be signed before the job is commenced or merchandise is delivered).

The undersigned is authorized to execute this contract as an agent of the customer. As such, the undersigned agrees and acknowledges that this contract for services, materials, products, and/or supplies includes all of and only those terms and conditions appearing on the front and back of this document. No additional or substitute terms and/or conditions shall become a part of this contract without the written consent of an officer of Basic Energy Services LP.

SIGNED: *[Signature]*
(WELL OWNER, OPERATOR, CONTRACTOR OR AGENT)

ITEM/PRICE REF. NO.	MATERIAL, EQUIPMENT AND SERVICES USED	UNIT	QUANTITY	UNIT PRICE	\$ AMOUNT
CP 103	60/40 Poz Cement	SK	210		
CC 200	Cement Gel	Lb	362		
E 100	Pickup Mileage	mi	45		
E 101	Heavy Equipment Mileage	mi	90		
E 113	Bulk Delivery	tm	407		
CE 204	Cement Pump: 3,000 Feet To 4,000 Feet	hrs.	4		
CE 240	Blending and Mixing Service	SK	210		
5003	Service Supervisor	hrs.	8		

CHEMICAL / ACID DATA:

SUB TOT **DLS**
SERVICE & EQUIPMENT %TAX ON \$
MATERIALS %TAX ON \$

TOTAL

SERVICE REPRESENTATIVE *[Signature]*

THE ABOVE MATERIAL AND SERVICE ORDERED BY CUSTOMER AND RECEIVED BY: *[Signature]*

(WELL OWNER OPERATOR CONTRACTOR OR AGENT)

FIELD SERVICE ORDER NO.

BASIC

energy services, L.P.

TREATMENT REPORT

Customer G. Holl Company, LLC.	Lease No.	Date 10-2-11
Lease Neeland Trust	Well # 1-21	
Field Order # 5117	Station Pratt, Kansas	Casing 1 1/2 Drill Pipe
Type Job C.N.W. - Plug To Abandon	Formation	County Stafford
		State Kansas
		Legal Description 21-225-14W

PIPE DATA		PERFORATING DATA		MATERIALS USED		TREATMENT RESUME		
Casing Size	Tubing Size	Sbts/Bt		210 sacks	60/40 Poz	PRESS	ISIP	
Depth	Depth	From	To	13.8 lb/Gal	Max 8.5 Gal/stk	48 Gal	5 Min	2 CV.F.T./stk
Volume	Volume	From	To		Min		10 Min.	
Max Press	Max Press	From	To		Avg		15 Min.	
Wall Connection	Annulus Vol.	From	To		HHP Used		Annulus Pressure	
Plug Depth	Packer Depth	From	To	Flush	Drilling mud and Fresh Water	Gas Volume	Total Load	

Customer Representative Steve Stephens	Station Manager David Scott	Treater Clarence R. Messick
---	--------------------------------	--------------------------------

Service Units	37,216	33,768	20,920	19,831	19,862				
Driver Names	Messick	Gibson	Young						

Time P.M.	Casing Pressure	Tubing Pressure	Bbls. Pumped	Rate	Service Log
3:30					Cementer and pump truck on location
4:30					Cement on location and hold safety meeting
5:03					1 st /Plug 3,920 Feet - 50 sacks cement
		500		5	start Fresh Water Pre-Flush.
		550	20	5	Start Mixing cement
		300	32.5	5	Start Fresh Water Displacement
		200	42.5	5	Start Drilling mud Displacement
5:20	-0-	80			Stop pumping.
					2 nd /Plug 900 Feet - 50 sacks cement
6:45		300		5	start Fresh Water Pre-Flush
		300	10	5	start Mixing cement
		100	22.5	5	Start Fresh Water Displacement
6:51	-0-	27.5			Stop pumping.
					3 rd /Plug 300 Feet - 40 sacks Cement
7:05		100		3.5	Start mixing cement
		-0-	10	3.5	Start Fresh Water Displacement
7:10	-0-	11			Stop pumping.
					4 th /Plug 60 Feet - 20 sacks cement
8:12				3	start mixing cement
8:19	-0-	5			cement circulated to surface. Stop pumping.
	-0-	7.5		3	Plug Rat and Mouse Holes
					Wash up pump truck