

a111611-q


Pro-Stake LLC

Oil Field & Construction Site Staking

P.O. Box 2324

Garden City, Kansas 67846 Office/Fax: (620) 276-6159

Cell: (620) 272-1499



Ritchie Exploration, Inc.

Ford County, KS

COUNTY

OPERATOR

7 26s 22w

#1 Herron

515' FNL - 2305' FEL

LOCATION SPOT

SCALE: 1" =1000'

DATE STAKED: Nov. 16th, 2011

MEASURED BY: Ben R.

DRAWN BY: Luke R.

AUTHORIZED BY: Justin C.


This drawing does not constitute a monumented survey or a land survey plat.

This drawing is for construction purposes only.

GR. ELEVATION: 2418.3'

Directions: From the NW side of Spearville, Ks at the intersection of Hwy 50 & Main St. SE – Now go 0.4 mile SE on Main St. – Now go 0.1 mile East on Davis St. – Now go 1.5 miles South on Ford Spearville Rd – Now go 0.4 mile West on Correction Line Rd – Now go 1 mile South on 125 Rd to the NE corner of section 7-26s-22w – Now go 0.4 mile West on Horseshoe Rd to ingress South into – Now go 515' South through wheat stubble into staked location.

Final ingress must be verified with land owner or Operator.






a111611-q

Pro-Stake LLC

Oil Field & Construction Site Staking

P.O. Box 2324

Garden City, Kansas 67846 Office/Fax: (620) 276-6159 Cell: (620) 272-1499



Ritchie Exploration, Inc.

Ford County, KS

COUNTY

OPERATOR

7 26s 22w Sec. Tup. Rog. LEASE NAME 515' FNL – 2305' FEL

LOCATION SPOT

#1 Herron

SCALE: N/A

DATE STAKED: Nov. 16th, 2011

MEASURED BY: Ben R.

DRAWN BY: Luke R.

AUTHORIZED BY: Justin C.

This drawing does not constitute a monumented survey or a land survey plat.

This drawing is for construction purposes only.

GR. ELEVATION: .2418.3'

Directions: From the NW side of Spearville, Ks at the intersection of Hwy 50 & Main St. SE – Now go 0.4 mile SE on Main St. – Now go 0.1 mile East on Davis St. – Now go 1.5 miles South on Ford Spearville Rd – Now go 0.4 mile West on Correction Line Rd – Now go 1 mile South on 125 Rd to the NE corner of section 7-26s-22w – Now go 0.4 mile West on Horseshoe Rd to ingress South into – Now go 515' South through wheat stubble into staked location.

Final ingress must be verified with land owner or Operator.

