



PAGE 1 of 1	CUST NO 1001376	INVOICE DATE 06/22/2012
INVOICE NUMBER <b>1718 - 90935546</b>		

Pratt (620) 672-1201  
 B F.G. HOLL COMPANY LLC  
 I PO Box: 308  
 L ELLINWOOD  
 L KS US 67526  
 T  
 O ATTN: ACCOUNTS PAYABLE

J LEASE NAME Panning 2-13  
 O LOCATION  
 B COUNTY Barton  
 S STATE KS  
 I JOB DESCRIPTION Cement-New Well Casing/Pi  
 T JOB CONTACT  
 E

JOB #	EQUIPMENT #	PURCHASE ORDER NO.	TERMS	DUE DATE	
40478350	27463		Net - 30 days	07/22/2012	
		QTY	U of M	UNIT PRICE	INVOICE AMOUNT
For Service Dates: 06/21/2012 to 06/21/2012					
0040478350					
<div style="border: 1px solid black; padding: 5px; display: inline-block;"> <b>PAID</b>            JUL 18 2012            63787         </div>					
171805929A Cement-New Well Casing/Pi 06/21/2012					
Cement 4 1/2" Longstring					
<div style="border: 1px solid black; padding: 5px; display: inline-block;"> <i>Received</i>            JUN 20 2012  <b>ROB LONG</b> </div>					
AA2-Cement		175.00	EA	13.60	
60/40 POZ		75.00	EA	9.60	
Celloflaka		44.00	EA	2.96	
C-41L		42.00	EA	3.20	
Salt		786.00	EA	0.40	
C-44		165.00	EA	4.12	
FLA-322		165.00	EA	6.00	
Super Flush		500.00	EA	1.96	
Gilsonite		2,125.00	EA	0.54	
"Latch Down Plug & Baffle, 4 1/2" (Blue)		1.00	EA	295.99	
"Auto Fill Float Shoe 4 1/2" (Blue)"		1.00	EA	263.99	
"Turbolizer, 4 1/2" (Blue)"		10.00	EA	68.00	
Cement Scratchers Rotating Type		50.00	EA	40.00	
4 1/2" Basket(Blue)		1.00	EA	215.99	
"Unit Mileage Chg (PU, cars one way)"		55.00	MI	3.40	
Heavy Equipment Mileage		110.00	MI	5.60	
"Proppant & Bulk Del. Chgs., per ton mil		633.00	EA	1.28	
Depth Charge; 3001-4000'		1.00	EA	1,727.93	
Blending & Mixing Service Charge		250.00	BAG	1.12	
Casing Swivel Rental		1.00	EA	159.99	
Plug Container Util. Chg.		1.00	EA	199.99	
"Service Supervisor, first 8 hrs on loc.		1.00	EA	139.99	

ENT'D JUL 08 2012

PLEASE REMIT TO:

SEND OTHER CORRESPONDENCE TO:

BASIC ENERGY SERVICES, LP  
 PO BOX 841903  
 DALLAS, TX 75284-1903

BASIC ENERGY SERVICES, LP  
 PO BOX 10460  
 MIDLAND, TX 79702

SUB TOTAL

TAX

INVOICE TOTAL

MAY-29-2004 18:43 From: BASIC ENERGY SERVICE 620 672 7019 To: 316 684 0594 P.3/3



**TREATMENT REPORT**

Customer: FG Hall Co LLC Lease No. \_\_\_\_\_ Date: \_\_\_\_\_  
 Well #: 2-13  
 Field Order #: 05929A Station: Pratt Casing: 4 1/2" Depth: 3749' County: Barton State: Kc  
 Type Job: 4 1/2" L.S. Formation: TD 3750 Legal Description: 17-20-17

PIPE DATA		PERFORATING DATA		FLUID USED		TREATMENT RESUME		
Casing Size: <u>4 1/2"</u>	Tubing Size: _____	Shots/Ft: _____	From: _____	To: _____	Acid: <u>12 BBL super Flush</u>	RATE: _____	PRESS: _____	ISIP: _____
Depth: <u>3749'</u>	Depth: _____	From: _____	To: <u>255'</u>	To: _____	Pre Pad: <u>25 Sks 60/40 Per</u>	Max: <u>Scavenger @ 14 1/2 gal</u>	Min: <u>5 Min.</u>	Min: <u>10 Min.</u>
Volume: <u>57</u>	Volume: _____	From: _____	To: <u>175</u>	To: _____	Post: <u>5 Sks AA2 @ 15 #/gal</u>	Mix: _____	Avg: _____	15 Min.
Max Press: <u>1500'</u>	Max Press: _____	From: _____	To: _____	To: _____	Frac: _____	HHP Used: _____	Annulus Pressure: _____	Total Load: _____
Well Connection: <u>P.C.</u>	Annulus Vol: _____	From: _____	To: _____	To: _____	Flush: <u>Disp H2O</u>	Gas Volume: _____	Annulus Pressure: _____	Total Load: _____
Plug Depth: <u>3717'</u>	Packer Depth: _____	From: _____	To: _____	To: _____	Flush: <u>Disp H2O</u>	Gas Volume: _____	Annulus Pressure: _____	Total Load: _____

Customer Representative: Rob Lutz Station Manager: scotty Treater: Allen

Service Units: <u>23443</u>	<u>27463</u>	<u>19831</u>	<u>19862</u>					
Driver Names: <u>Allen</u>	<u>Eric</u>	<u>Jessie</u>	<u>Pearson</u>					

Time	Casing Pressure	Tubing Pressure	Bble. Pumped	Rate	Service Log
10:00 AM					on loc. Discuss Safety Setup Plan Job
					Laying down Kelly - Rig up to
					Run 4 1/2" casing 10.5 #/ft
11:00					Start 4 1/2" csg. Shoe Joint 31.69'
					w/ float shoe, + L.O. Baffle in collar
					cent-2-3-4-5-6-7-8-9-10-11 Basket #7
1:00 PM					Tac Bottom pickup to 3749' + cir.
3:00	200'		5	5	Pump 5 BBL H2O
			10	5	Pump 12 BBL super Flush
			5	5	Pump 5 BBL H2O
			6	5	mix 25 Sks 60/40 scavenger 14 #
			4 1/2		mix 175 Sks AA2 @ 15 #
					Finish mix, wash out pump + line
				6	Drop L.O. Plug, Start Disp.
	500		28	5	Caught lift 30 BBL
3:30	1500'		59	4	Plug down - Release PST - OK
			7		Plug RH w/ 30 Sks 60/40
			5		Plug MH w/ 20 Sks 60/40
					wash up Equip + Rack up.
					Job complete.
					thanks Allen, Eric, Jessie