



**CONSOLIDATED**  
Oil Well Services, LLC

SCANNED  
ENTERED

TICKET NUMBER 34562  
LOCATION Eureka  
FOREMAN Rick Ledford

PO Box 884, Chanute, KS 66720  
620-431-9210 or 800-467-8676

**FIELD TICKET & TREATMENT REPORT**

**CEMENT** API# 15-107-24598

DATE	CUSTOMER #	WELL NAME & NUMBER	SECTION	TOWNSHIP	RANGE	COUNTY
4-18-12	1828	Ungeheuer #E-8	33	21	22E	LINN
CUSTOMER <u>Colt Energy, Inc</u>			TRUCK #			
MAILING ADDRESS <u>P.O. Box 388</u>			DRIVER		TRUCK #	
CITY <u>Iola</u>			DRIVER		TRUCK #	
STATE <u>KS</u>			DRIVER		TRUCK #	
ZIP CODE <u>66749</u>			DRIVER		TRUCK #	

JOB TYPE L/S 0 HOLE SIZE 7 7/8 HOLE DEPTH 860 CASING SIZE & WEIGHT 5 1/2, 15.50  
 CASING DEPTH 820.5 DRILL PIPE \_\_\_\_\_ TUBING \_\_\_\_\_ OTHER \_\_\_\_\_  
 SLURRY WEIGHT 13.6# SLURRY VOL 37 Bbl WATER gal/sk 9.0 CEMENT LEFT in CASING 5' ST  
 DISPLACEMENT 19.4 Bbl DISPLACEMENT PSI 600 ~~PSI/1000# Bump plus~~ RATE \_\_\_\_\_

REMARKS: Safety meeting - Rig up to 5 1/2" casing w/ wash head. Washdown 15' to PBTD.  
Mixed 60 sks gel-flush, 15 Bbl water spacer. Mixed 100 sks OWC cement w/ 40% silica flour @ 13.6#/gal. Washout pump & lines, release plug. Displace w/ 19.4 Bbl fresh water. Final pump pressure 600 PSF. Bump plus to 1000 PSF. Wait 2 minutes, release pressure, float & plug hold. Good cement returns to surface = 5 Bbl slurry to pit. Job complete. Rig down.

"Thank You"

ACCOUNT CODE	QUANTITY or UNITS	DESCRIPTION of SERVICES or PRODUCT	UNIT PRICE	TOTAL
5401	1	PUMP CHARGE	1030.00	1030.00
5406	50	MILEAGE from 1st well to 2nd well	4.00	200.00
1126	100 sks	OWC cement	18.80	1880.00
1139	3260 #	40% silica flour	.53	1992.80
1118B	300 #	gel-flush	.21	63.00
5407A	7	tan mileage bulk trk	1.34	469.00
4406	1	5 1/2" top rubber plug	70.00	70.00
			Subtotal	5704.80
			SALES TAX	252.37
			ESTIMATED TOTAL	5957.17

Ravin 3737

AUTHORIZATION R. R. Ledford

TITLE 249201

DATE 4/18/2012

I acknowledge that the payment terms, unless specifically amended in writing on the front of the form or in the customer's account records, at our office, and conditions of service on the back of this form are in effect for services identified on this form.