



CONSOLIDATED
Oil Well Services, LLC

ENTERED

TICKET NUMBER 35254

LOCATION Europe

FOREMAN Rick Ledford

PO Box 884, Chanute, KS 66720
620-431-9210 or 800-467-8676

FIELD TICKET & TREATMENT REPORT

CEMENT API# 15-107-24634

DATE	CUSTOMER #	WELL NAME & NUMBER	SECTION	TOWNSHIP	RANGE	COUNTY
9-17-12	1829	Lanham (363) #A3	2	22	22E	LIQU
CUSTOMER <u>Colt Energy Inc.</u>						
MAILING ADDRESS <u>P.O. Box 388</u>						
CITY <u>Iola</u>		STATE <u>KS</u>	ZIP CODE <u>66749</u>			
TRUCK #	DRIVER	TRUCK #	DRIVER			
520	John					
611	Joey					
667	Chris B.					
637	Jim					

JOB TYPE L/S 0 HOLE SIZE 7 7/8" HOLE DEPTH 687 CASING SIZE & WEIGHT 5 1/2" 15.5"
 CASING DEPTH 686 DRILL PIPE _____ TUBING _____ OTHER _____
 SLURRY WEIGHT 13.5# SLURRY VOL 30 Bbl WATER gal/sk 9.0 CEMENT LEFT in CASING 20'
 DISPLACEMENT 15 3/4" DISPLACEMENT PSI 250# MAX PSI 200 shut in RATE _____

REMARKS: Safety meeting. Rig up to 5 1/2" casing w/washhead. Wash down to BSTD. Rig up to cement. Pump 6 sks gel-flush, 5 Bbl water spacer, 8 Bbl dye water. Mixed 80 sks OWC cement w/ 40% silica flour @ 13.5#/gal. shut down, washout pump & lines, stuff plug. Displace w/ 15 3/4 Bbl water to 666' followed by wireline. Final pump pressure 250 PSI. Closed well in @ 200 PSI. Good cement returns to surface ~ 5 Bbl slurry to pit. Job complete Rig down.

"Thank You"

ACCOUNT CODE	QUANTITY or UNITS	DESCRIPTION of SERVICES or PRODUCT	UNIT PRICE	TOTAL
5401	1	PUMP CHARGE	1030.00	1030.00
5406	1	MILEAGE 2 nd well of 3	n/c	n/c
1126	80 sks	OWC cement	18.80	1504.00
1139	3010 #	40% silica flour	.53	1595.30
1118B	300 #	gel-flush	.21	63.00
5407A	5.6	tan mileage bulk tax	1.34	375.20
5502C	3 1/2 hrs	80 Bbl VAC. TAX	90.00	315.00
4406	1	5 1/2" top water plug	70.00	70.00
			Subtotal	4952.50
			6.3% SALES TAX	203.63
			ESTIMATED TOTAL	5156.13

Ravin 3737

AUTHORIZATION

R.R. Block

TITLE

263140

DATE

9/19/2012

I acknowledge that the payment terms, unless specifically amended in writing on the front of the form or in the customer's account records, at our office, and conditions of service on the back of this form are in effect for services identified on this form.