



BASICSM
ENERGY SERVICES

PRESSURE PUMPING & WIRELINE

10244 NE Hwy. 61
P.O. Box 8613
Pratt, Kansas 67124
Phone 602-672-1201

11400 1011
FIELD SERVICE TICKET

1718 07095 A

DATE _____ TICKET NO. _____

DATE OF JOB <i>1-8-13</i> DISTRICT <i>Kansas</i>		NEW WELL <input checked="" type="checkbox"/> OLD WELL <input type="checkbox"/> PROD <input type="checkbox"/> INJ <input type="checkbox"/> WDW <input type="checkbox"/> CUSTOMER ORDER NO.:							
CUSTOMER <i>FG Holl Co. LLC.</i>		LEASE <i>Menzer #1-22</i> WELL NO.:							
ADDRESS		COUNTY <i>Barton 22-17-13</i> STATE <i>Ks</i>							
CITY STATE		SERVICE CREW <i>Allen</i>							
AUTHORIZED BY		JOB TYPE: <i>8 5/8" Surface</i> <i>CNW</i>							
EQUIPMENT#	HRS	EQUIPMENT#	HRS	EQUIPMENT#	HRS	TRUCK CALLED	DATE	AM	TIME
<i>78443 PH</i>	<i>1</i>					<i>1-8-13</i>	<i>1-8-13</i>	<i>AM</i>	<i>115</i>
<i>19889-19843</i>	<i>1</i>					ARRIVED AT JOB	<i>1-8-13</i>	<i>AM</i>	<i>415</i>
<i>19960-7376</i>	<i>1</i>					START OPERATION	<i>1-8-13</i>	<i>AM</i>	<i>1050</i>
						FINISH OPERATION	<i>1-8-13</i>	<i>AM</i>	<i>1130</i>
						RELEASED	<i>1-8-13</i>	<i>AM</i>	<i>1230</i>
						MILES FROM STATION TO WELL			<i>70-mile</i>

CONTRACT CONDITIONS: (This contract must be signed before the job is commenced or merchandise is delivered).

The undersigned is authorized to execute this contract as an agent of the customer. As such, the undersigned agrees and acknowledges that this contract for services, materials, products, and/or supplies includes all of and only those terms and conditions appearing on the front and back of this document. No additional or substitute terms and/or conditions shall become a part of this contract without the written consent of an officer of Basic Energy Services LP.

SIGNED: _____
(WELL OWNER, OPERATOR, CONTRACTOR OR AGENT)

ITEM/PRICE REF. NO.	MATERIAL, EQUIPMENT AND SERVICES USED	UNIT	QUANTITY	UNIT PRICE	\$ AMOUNT
CF101	A-Con Blend Cement	SK	200		
CF1006	Common Cement	SK	200		
CC102	Cell Flake	lb	100		
CC109	Calcium Chloride	lb	940		
CF105	Top Rubber cement Plug 8 5/8"	EA	1		
CF1753	Cart 8 5/8" Blue	EA	3		
F160	Unit mileage chg. P.U.	Mi	70		
F101	Heavy Equip mileage	Mi	140		
F113	Bulk Delivery Charge	TM	1316		
CE301	Depth Charge 501-1000'	4-hr	1		
CE240	Bleeding + mixing Service chg	SK	400		
CE504	Plug container Utilization chg Job	Job	1		
S003	Service Supervisor First 8 hrs	EA	1		

SUB TOTAL

CHEMICAL / ACID DATA:			

SERVICE & EQUIPMENT	%TAX ON \$		
MATERIALS	%TAX ON \$		
TOTAL			

SERVICE REPRESENTATIVE <i>Allen Wood</i>	THE ABOVE MATERIAL AND SERVICE ORDERED BY CUSTOMER AND RECEIVED BY: <i>Deon Vasquez</i>
(WELL OWNER OPERATOR CONTRACTOR OR AGENT)	

FIELD SERVICE ORDER NO.

BASIC

energy services, L.P.

TREATMENT REPORT

Customer FG Hall Co. LLC	Lease No.	Date 1-8-13
Lease MENZER	Well # 1-22	
Field Order # 07095	Station Pratt KS	Casing 8 5/8
	Depth 1033	County Barton
Type Job 8-5/8" Surface	Formation CNW	Legal Description TD 1033 22-17-15

PIPE DATA		PERFORATING DATA		FLUID USED		TREATMENT RESUME		
Casing Size 8 5/8	Tubing Size	Shots/Ft		Acid	RATE	PRESS	ISIP	
Depth 1033	Depth	From	To	Pre Pad	Max		5 Min.	
Volume 64	Volume	From	To	Pad	Min		10 Min.	
Max Press # 400	Max Press	From	To	Frac	Avg		15 Min.	
Well Connection PC	Annulus Vol.	From	To		HHP Used		Annulus Pressure	
Plug Depth 1013	Packer Depth	From	To	Flush Disp H 20	Gas Volume		Total Load	

Customer Representative Dean TP	Station Manager Scotty	Treater Allen
Service Units 28443 19889 19843 19960 73765		
Driver Names Allen Edmundo Steve Young		

Time	Casing Pressure	Tubing Pressure	Bbls. Pumped	Rate	Service Log
4:15 PM					on Loc. Discuss Safety, Setup Plan Job
					Rig Drilling @ 996'
5:45					Start out of Hole - 'Short Trip'
6:30					Start BACK IN Hole w/ Bit
7:05					Back in Hole w/ Bit + CIR.
7:45					Start out of Hole w/ Bit
8:20					out of Hole, Rig up to RW 8 5/8"
					Casing 23#
9:00					St. 8 5/8" csg. Cent 900' - 450' - 40'
10:25					Casing @ 1033' CIR w/ Rig
10:50	200#		88	5 1/2	Mix 200SKs A-CON @ 12#
10:50				5 1/2	Mix 200SKs common 20% CC, 1/4# C.F. @ 15.6#
			43		Finish mit
					Release Top Rubber Plug 8 5/8"
11:20				5 1/2	start Disp.
11:30	300#		64	3	Plug down
	0#				Shut IN @ well Circ 29sk (mit)
					Release PSI To Truck
					wash up Equip. + Pack up
12:30					Job complete.
					Thanks Allen, Eddie, Steve