



BASIC
ENERGY SERVICES

6076
711 BANTA F
6438

PAGE 1 of 1	CUST NO 1007589	INVOICE DATE 02/25/2013
INVOICE NUMBER 1718 - 91126139		

Pratt (620) 672-1201
HERMAN L LOEB LLC
PO Box: 838
LAWRENCEVILLE
IL US 62439
ATTN: ACCOUNTS PAYABLE

J LEASE NAME Banta F 1-20
O LOCATION
B COUNTY Kiowa
S STATE KS
I JOB DESCRIPTION Cement-New Well Casing/Pi
T JOB CONTACT
E

JOB #	EQUIPMENT #	PURCHASE ORDER NO.	TERMS	DUE DATE
40567469	19905		Net - 30 days	03/27/2013

	QTY	U of M	UNIT PRICE	INVOICE AMOUNT
<i>For Service Dates: 02/18/2013 to 02/18/2013</i>				
0040567469				
171808051A Cement-New Well Casing/Pi 02/18/2013 Cement 5 1/2" Longstring				
50/50 POZ	250.00	EA	8.25	2,062.37 T
Celloflake	63.00	EA	2.77	174.82 T
Gypsum	1,050.00	EA	0.56	590.59 T
FLA-322	105.00	EA	5.62	590.59 T
Gilsonite	1,500.00	EA	0.50	753.71 T
Mud Flush	1,000.00	EA	0.64	644.97 T
KCL Potassium Chloride	566.00	EA	1.12	636.72 T
Claymax KCL Substitute	5.00	EA	26.25	131.24 T
"Latch Down Plug & Baffle, 5 1/2" (Blue)"	1.00	EA	299.98	299.98
"Auto Fill Float Shoe 5 1/2" (Blue)"	1.00	EA	269.99	269.99
"Turbolizer, 5 1/2" (Blue)"	12.00	EA	82.50	989.95
"5 1/2" Basket (Blue)"	1.00	EA	217.49	217.49
"Cement Scratchers Cable Type, 5 1/2" "	6.00	EA	56.25	337.48
"Unit Mileage Chg (PU, cars one way)"	35.00	MI	3.19	111.56
Heavy Equipment Mileage	70.00	MI	5.25	367.48
"Proppant & Bulk Del. Chgs., per ton mil	368.00	EA	1.20	441.58
Depth Charge; 4001'-5000'	1.00	EA	1,889.90	1,889.90
Blending & Mixing Service Charge	250.00	BAG	1.05	262.49
Plug Container Util. Chg.	1.00	EA	187.49	187.49
"Service Supervisor, first 8 hrs on loc.	1.00	EA	131.24	131.24

PLEASE REMIT TO:	SEND OTHER CORRESPONDENCE TO:	SUB TOTAL	11,091.64
BASIC ENERGY SERVICES, LP	BASIC ENERGY SERVICES, LP	TAX	407.71
PO BOX 841903	801 CHERRY ST, STE 2100	INVOICE TOTAL	11,499.35
DALLAS, TX 75284-1903	FORT WORTH, TX 76102		



BASICSM
ENERGY SERVICES
PRESSURE PUMPING & WIRELINE

10244 NE Hwy. 61
P.O. Box 8613
Pratt, Kansas 67124
Phone 620-672-1201

FIELD SERVICE TICKET

1718 ~~00052~~ A
Continuation


20-275-18W

DATE _____ TICKET NO. 8051

DATE OF JOB 2-18-13		DISTRICT _____		NEW WELL <input checked="" type="checkbox"/> OLD WELL <input type="checkbox"/>		PROD <input type="checkbox"/> INJ <input type="checkbox"/> WDW <input type="checkbox"/>		CUSTOMER ORDER NO. _____	
CUSTOMER Herman L. Loeb, LLC				LEASE Banta "F"				WELL NO. 1-20	
ADDRESS _____				COUNTY Kiowa		STATE Kansas			
CITY _____ STATE _____				SERVICE CREW C. Messick, M. Mattal, J. Pierson					
AUTHORIZED BY _____				JOB TYPE: C.N.W. - Longstring					
EQUIPMENT#	HRS	EQUIPMENT#	HRS	EQUIPMENT#	HRS	TRUCK CALLED	DATE	AM	TIME
						ARRIVED AT JOB		AM	PM
						START OPERATION		AM	PM
						FINISH OPERATION		AM	PM
						RELEASED		AM	PM
						MILES FROM STATION TO WELL _____			

CONTRACT CONDITIONS: (This contract must be signed before the job is commenced or merchandise is delivered).

The undersigned is authorized to execute this contract as an agent of the customer. As such, the undersigned agrees and acknowledges that this contract for services, materials, products, and/or supplies includes all of and only those terms and conditions appearing on the front and back of this document. No additional or substitute terms and/or conditions shall become a part of this contract without the written consent of an officer of Basic Energy Services LP.

SIGNED: 
(WELL OWNER, OPERATOR, CONTRACTOR OR AGENT)

ITEM/PRICE REF. NO.	MATERIAL, EQUIPMENT AND SERVICES USED	UNIT	QUANTITY	UNIT PRICE	\$ AMOUNT
P E 100	Pickup Mileage	mi	35	\$	148 75
P E 101	Heavy Equipment Mileage	mi	70	\$	490 00
P E 113	Bulk Delivery	tm	368	\$	588 00
P CE 205	Cement Pump: 4,000 Feet To 5,000 Feet	hrs	4	\$	2,520 00
P CE 240	Blending and Mixing Service	slr	250	\$	350 00
P CE 504	Plug Container	Job	1	\$	250 00
P S003	Service Supervisor	hrs	8	\$	175 00

CHEMICAL / ACID DATA:			

SUB TOTAL		NLS \$ 11,091 64
SERVICE & EQUIPMENT	%TAX ON \$	
MATERIALS	%TAX ON \$	
TOTAL		

SERVICE REPRESENTATIVE 	THE ABOVE MATERIAL AND SERVICE ORDERED BY CUSTOMER AND RECEIVED BY: 
--	---

(WELL OWNER OPERATOR CONTRACTOR OR AGENT)

FIELD SERVICE ORDER NO. _____

Customer Herman L. Loeb, LLC.	Lease No.	Date 2-18-13
Lease Banta "F"	Well # 1-20	
Field Order # 8051	Station Pratt, Kansas	Casing 5 1/2 15.5 LB
Type Job C.N.W. - Longstring	Formation	Depth 4,875 ft.
		County Kiowa
		State Kansas
		Legal Description 20-27S-18W

PIPE DATA		PERFORATING DATA		CEMENT USED		TREATMENT RESUME	
Casing Size 5 1/2 15.5 LB/ft.	Tubing Size 5 1/2 15.5 LB/ft.	Shots/Ft 200	From 25	To 25	Rate 28 Gal./Stk.	Pressure 58 kCL	ISIP 5 Min.
Depth 4,875 Feet	Depth	From	To	25 LB/ST. Cellplate, 6 L	Max 28 Gal./Stk.	Min 1.35 cu. ft.	10 Min.
Volume 116 Bbl.	Volume	From	To	14 LB/Gal., 5.4	Avg		15 Min.
Max Press 1,500 P.S.I.	Max Press	From	To				
Well Connection Plug Container	Annulus Vol. Racker Depth	From	To	50 sacks 50/50 Poz top plug Rat (30 sacks) and Mouse (20 sacks) holes	HHP used Gas Volume		Annulus Pressure Total Load
Plug Depth 4,875 Feet	From	To	Flush 115.6 Bbl. 28 kCL				

Customer Representative George Payne	Station Manager David Scott	Treater Clarence R. Messich
---	--------------------------------	--------------------------------

Service Units	37,216	19,959	19,905	19,960	21,010
Driver Names	Messich	Mattal	Pierson		

Time A.M.	Casing Pressure	Tubing Pressure	Bbls. Pumped	Rate	Service Log
1:45					Trucks on location and hold safety meeting.
3:30					Sterling Drilling start to run Auto Fill Float Shoe, Shoe Joint with Latch Down Baffle screwed into Collar and a total of Joints new 15.5 LB/ft. 5 1/2" casing. A Basket was installed above Collar #14. A Turbolizer was installed on Collars #1, 2, 3, 4, 5, 8, 10, 12, 17, 22 and #27. Casing in well. Circulate for 1 hour.
8:16		2,500			Shut in well. Pressure Test. Open well.
8:18	300			6	Start Fresh water Pre-Flush.
	300		20	6	Start mud Flush.
	300		44	6	Start Fresh water spacer.
8:28	400		64	5	Start mixing 200 sacks 50/50 Poz cement.
	-0-		112		Stop pumping. Shut in well. Wash pump and lines. Release Latch Down Plug. Open Well.
8:40	100			6.5	Start 28 kCL Displacement.
				5	Start to lift cement.
9:00	800		115.6		Plug down.
	1,500				Pressure up.
					Release pressure. Float Shoe held.
no	-0-		7.5	3	Plug Rat and mouse holes.
					Wash up pump truck.
9:45					Job Complete.
					Thank You.
					Clarence, Milte, Tesse