

JOB LOG

SWIFT Services, Inc.

DATE 5-17-13 PAGE NO. 7

CUSTOMER *Lowndes & Nelson* WELL NO. *232* LEASE *Mitchell-Davignon* JOB TYPE *Cement Lugs string* TICKET NO. *24589*

CHART NO.	TIME	RATE (BPM)	VOLUME (BBL) (GAL)	PUMPS		PRESSURE (PSI)		TD	DESCRIPTION OF OPERATION AND MATERIALS
				T	C	TUBING	CASING		
<i>5/17</i>	<i>2100</i>					<i>147#</i>	<i>5 1/2</i>	<i>TD 4062</i>	<i>On location / Floor Equip. Rig LDDC</i>
	<i>2220</i>								<i>Start 5 1/2 - 14 # / At 350 to 406 1/2</i>
									<i>Insert Float Shoe (2) / F71-100</i>
									<i>55-18' L.V. Baffle @ 4043 1/2</i>
									<i>Ceant 1-3-5-7-9-11-13-48</i>
									<i>Cement Baskets - 24-49 - Pin End</i>
									<i>D.V. Tool #49 @ 2063.56</i>
									<i>Drop ferrule ball 5 fts and</i>
<i>5/17</i>	<i>2345</i>								<i>Fin recessing - Tag & Log St Down</i>
<i>5/17</i>	<i>2400</i>								<i>Start CCR / Rotate casing</i>
<i>5/18</i>	<i>0030</i>								<i>Fin CCR - Ready for 1st stage</i>
		<i>5</i>	<i>12</i>						<i>Pump 50 gal Merd Flush</i>
		<i>6</i>	<i>20</i>						<i>Pump 20 BBL KCL Flush</i>
		<i>4 1/2</i>							<i>Start 150SK EA-2-cut</i>
		<i>4 1/2</i>	<i>36</i>						<i>Fin cut - Wash Pump Lines</i>
		<i>9</i>							<i>500 P.U.L.D Plug - Start Displ</i>
		<i>8</i>	<i>75</i>						<i>400 Caught cut 1st @ 25881</i>
		<i>5 1/2</i>	<i>98 1/2</i>						<i>1000 Plug Down - Hold - Release & Hold</i>
									<i>Drop D.V. Opening Tool</i>
									<i>Plug RH 30SKS SMD cut 14H-150SKS cut</i>
		<i>0 1/2</i>							<i>1150 Open D.V. - Fin Flush</i>
		<i>5 1/4</i>							<i>200 Start SMD cut</i>
									<i>Fin cut - Drop D.V. Closing Plug</i>
		<i>6</i>							<i>200 Start Displ</i>
	<i>0215</i>	<i>5</i>							<i>500 Plug Down - 10SKS center to Pet</i>
									<i>D.V. Closed - Release & Hold</i>
									<i>Job Complete</i>
	<i>0230</i>								<i>Washup & Racking TR</i>

Isaac
Isaac