CEMENT FIELD TICKET AND TREATMENT REPORT

stomer	Long & Ware	State, County	Chautauqua , Kansas	Cement Type	CL	ASS A
	LONG & VVAICE	Section	18	Excess (%)		40
Туре	cong pung	TWP	34\$	Density		14
storner Acct #	73 = 1		12E	Water Required		7.9
II No.	Von Merveldt #8	RGE	125	Yeild		1.74
iling Address		Formation		Sacks of Cement		140
y & State		Tubing			4	3.3bbl
Code		Drill Pipe		Slurry Volume		
		Casing Size	4 1/2"	Displacement		19.2
ntact		Hole Size	6 3/4"	Displacement PSI		500
naif				MIX PSI		200
11		Casing Depth	1207'			4bpm
spatch Location	BARTLESVILLE	Hole Depth		Rate		чирн
	Cement Pump Charges and Mileage	Quantity	Unit	Price per Unit	L	
de	CEMENT PUMP (2 HOUR MAX)	1	2 HRS MAX	\$1,085.00	\$	1,085.00
5401		1207	PER FOOT	\$0.23	\$	277.61
5402	FOOTAGE	40	PER MILE	\$4.20	\$	168.00
5406	EQUIPMENT MILEAGE (ONE-WAY)		PER LOAD	\$368.00	\$	368.00
5407	MIN. BULK DELIVERY (WITHIN 50 MILES)	1		\$0.00	\$	
0			0		\$	
0			00	\$0.00		
0			0	\$0.00	\$	
			0	\$0.00	\$	
0			0	\$0.00	\$	-
0		<u> </u>		EQUIPMENT TOTAL	\$	1,898.61
		т		1	$\overline{}$	
	Cement, Chemicals and Water	<u> </u>	 	\$19.75	\$	2,765.00
1126	WC. CEMENT (CAL SEAL) 6%OWC. 2% CAL.CLORIDE 2% GE	140	0			
	PREMIUM GEL/BENTONITE (50#)	200	0	\$0.22	\$	44.00
1118B	PHENOSEAL	80	0	\$1.35	\$	108.00
1107A		850	0	\$0,46	\$	391.00
1110A	KOL SEAL (50 # SK)		0	\$0.39	\$	351.00
1111	GRANULATED SALT (50#) SELL BY #	900	1 0	\$0.00	\$	-
0				\$0.00	\$	
0		l	00			_
_ 0		T	0	\$0.00	\$	
			0	\$0.00	\$	
0			0	\$0.00	\$	
0		 	0	\$0.00	\$	
0		 	0	\$0.00	\$	-
0			1	\$0.00	\$	
0		<u> </u>	0		\$	95.15
1123	CITY WATER (PER 1000 GAL)	5500	Per 1000 Gal	\$17.30		3,754.15
1123				Chemical Tota	1 \$	3,734.10
		T	T .	3.		
	Coment Water Transports 80 BBL VACUUM TRUCK (CEMENT)	5	BL VACUUM TRUCK (CE	M \$100.00	\$	500.00
5502C	80 BBL VACUUM TRUCK (CEMENT)	5	BL VACUUM TRUCK (CE	M \$100.00	\$	500.00
5502C	80 BBL VACUUM TRUCK (CEMENT)	 	0	\$0.00	\$	
0			<u> </u>	Transports Tota	s S	1,000.00
				Transports row	-	
	Cement Floating Equipment (TAXABLE)					1 1 1 1
						V. 3-2 1 1 1
44			0	\$0.00	\$	
0					0.000	
	Controller		0	\$0.00	\$	
0			0	\$0.00	5	
0				40.00		
	Float Shoe	Miller William			\$	
<u> </u>		_	0	\$0.00		111111111111111111111111111111111111111
0	Pitos College	A. A. C.				
	7 - Table (4 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 -		0	\$0.00	\$	<u>-</u>
0						Asset 5
	Guide Shoes		1 0	\$0.00	\$	
0						
	Beffie and Flapper Plates	<u> </u>		\$0.00	\$	-
0			0	W .00		1.413
	Packer Shoes			7	T.	
			0 ~	\$0.00	\$	
0		againg Mew J				<u> </u>
	DV Tools		0	\$0.00	\$	_
0						
T. 177 . 75.	Balt Valves, Swedges, Clamps, Misc.		- 1 0	\$0.00	\$	-
0				\$0.00	\$	
0			0		\$	
			0	\$0.00		
0 _	Plugs and Bell Sealers	100				47.
	4' 1/2" RUBBER PLUG	1	PER UNIT	\$47.25	\$	47.
	1 4° 1/2" RUBBER PLUG	- A T T E :				1.17-6571149
4404			0	\$0.00	\$	
4404	Downhole Tools		A STATE OF THE PARTY OF THE PAR	G EQUIPMENT TOTA	L 5	47.
4404			CEMENT FLUATIN			6,700
	Downhole Tools		CEMENT FLOATIN	0 SORION	/L \$	0,700
	Downhole Tools DRIVER NAME			0 SUBTOTA	XX 1	2011
	Downhole Tools DRIVER NAME Kirk Sanders			0 SUBTOTA 0% SALES TO TOT	AX 3	7.00
0	Downhole Tools DRIVER NAME Kirk Sanders Bryan Scullawi		8.3	0 SUBTOTA	AX 3	7,00°1 335
577	DRIVER NAME Kirk Sanders Bryan Scullawl Johnnie Goad		8.3	0 SUBTOTA 0% SALES TO TOT 5% (-DISCOUN	AX S	7,00°1 335
577 398	Downhole Tools DRIVER NAME Kirk Sanders Bryan Scullawi		8.3	0 SUBTOTA 0% SALES TOT	AX S	6,659.3
577 398	DRIVER NAME Kirk Sanders Bryan Scullawl Johnnie Goad		8.3	0 SUBTOTA 0% SALES TO TOT 5% (-DISCOUN	AX S	7.00 335
577 398	DRIVER NAME Kirk Sanders Bryan Scullawl Johnnie Goad		8.3	0 SUBTOTA 0% SALES TO TOT 5% (-DISCOUN	AX S	7.00 335
577 398	DRIVER NAME Kirk Sanders Bryan Scullawl Johnnie Goad		8.3	0 SUBTOTA 0% SALES TO TOT 5% (-DISCOUN	AX S	7.00 335
577 398	DRIVER NAME Kirk Sanders Bryan Scullawd Johnnie Goad H20 XPRESS 80 VAC x 2		8.3	0 SUBTOTA 0% SALES TO TOT 5% (-DISCOUN	AX S	7.00 335

I ACKNOWLEDGE THAT THE PAYMENT TERMS, UNLESS SPECIFICALLY AMENDED IN WRITING ON THE FRONT OF THE FORM OR IN THE CUSTOMER'S ACCOUNT RECORDS, AT OUR OFFICE, AND CONDITIONS OF SERVICE ON THE BACK OF THIS FORM ARE IN EFFECT FOR SERVICES IDENTIFIED ON THIS FORM.