



**BASIC**<sup>SM</sup>  
ENERGY SERVICES  
PRESSURE PUMPING & WIRELINE

10244 NE Hwy. 61  
P.O. Box 8613  
Pratt, Kansas 67124  
Phone 620-672-1201

FIELD SERVICE TICKET  
1718 09571 A

DATE \_\_\_\_\_ TICKET NO. \_\_\_\_\_

DATE OF JOB: 12-21-13		DISTRICT: Pratt		NEW WELL <input checked="" type="checkbox"/>		OLD WELL <input type="checkbox"/>		PROD <input type="checkbox"/>		INJ <input type="checkbox"/>		WDW <input type="checkbox"/>		CUSTOMER ORDER NO.:	
CUSTOMER: I G Hall Co LLC				LEASE: Scott Clark 31 931				WELL NO.:							
ADDRESS:				COUNTY: Pawnee				STATE: KS							
CITY:				STATE:				SERVICE CREW: MORTAL, KENNEDY, JONES							
AUTHORIZED BY:				JOB TYPE: COW LS											
EQUIPMENT#	HRS	EQUIPMENT#	HRS	EQUIPMENT#	HRS	TRUCK CALLED	DATE	AM	PM	TIME					
37550	1						12-21-13			8:00					
						ARRIVED AT JOB				12:30					
						START OPERATION				4:45					
27463	1					FINISH OPERATION				5:00					
						RELEASED				6:00					
19551/19552	1					MILES FROM STATION TO WELL				6.5					

CONTRACT CONDITIONS: (This contract must be signed before the job is commenced or merchandise is delivered).

The undersigned is authorized to execute this contract as an agent of the customer. As such, the undersigned agrees and acknowledges that this contract for services, materials, products, and/or supplies includes all of and only those terms and conditions appearing on the front and back of this document. No additional or substitute terms and/or conditions shall become a part of this contract without the written consent of an officer of Basic Energy Services LP.

SIGNED: \_\_\_\_\_  
(WELL OWNER, OPERATOR, CONTRACTOR OR AGENT)

ITEM/PRICE REF. NO.	MATERIAL, EQUIPMENT AND SERVICES USED	UNIT	QUANTITY	UNIT PRICE	\$ AMOUNT
CP 100	AA 2 000	EA	125		
CP 100	COAL 000	EA	75		
CC 100	C-1106100	10	32		
CC 105	C-41 P-11000	10	30		
CC 111	SALT	10	70		
CC 115	C 44	10	118		
CC 127	F 10 322	10	115		
CC 201	S 15 000	10	1629		
CC 607	...				
CC 1751	...				
CC 1051	...				
CC 1951	...				
CC 2002	...				
CC 151	...				

SUB TOTAL

CHEMICAL / ACID DATA:			

SERVICE & EQUIPMENT	%TAX ON \$	
MATERIALS	%TAX ON \$	
TOTAL		

SERVICE REPRESENTATIVE: Mike ...	THE ABOVE MATERIAL AND SERVICE ORDERED BY CUSTOMER AND RECEIVED BY: X R. ...
FIELD SERVICE ORDER NO.:	(WELL OWNER OPERATOR CONTRACTOR OR AGENT)



**BASIC**<sup>SM</sup>

ENERGY SERVICES  
PRESSURE PUMPING & WIRELINE

10244 NE Hwy. 61  
P.O. Box 8613  
Pratt, Kansas 67124  
Phone 620-672-1201

FIELD SERVICE TICKET

~~1718 09572~~ A

CONTINUATION OF 09571

DATE \_\_\_\_\_ TICKET NO. \_\_\_\_\_

DATE OF JOB: 12-21-13		DISTRICT: Pratt		NEW WELL <input checked="" type="checkbox"/> OLD WELL <input type="checkbox"/>		PROD <input type="checkbox"/> INJ <input type="checkbox"/> WDW <input type="checkbox"/>		CUSTOMER ORDER NO.:	
CUSTOMER: <del>SCOTT CLARK JR</del> GFS-Holl CO 11C				LEASE: SCOTT CLARK JR, 657 7451, WELL NO. 1-23					
ADDRESS:				COUNTY: Pawnee		STATE: KS			
CITY:				STATE:		SERVICE CREW:			
AUTHORIZED BY:				JOB TYPE: <i>CW CONSTRUCTION</i>					
EQUIPMENT#	HRS	EQUIPMENT#	HRS	EQUIPMENT#	HRS	TRUCK CALLED	DATE	AM	TIME
						ARRIVED AT JOB		AM	PM
						START OPERATION		AM	PM
						FINISH OPERATION		AM	PM
						RELEASED		AM	PM
						MILES FROM STATION TO WELL			

CONTRACT CONDITIONS: (This contract must be signed before the job is commenced or merchandise is delivered).

The undersigned is authorized to execute this contract as an agent of the customer. As such, the undersigned agrees and acknowledges that this contract for services, materials, products, and/or supplies includes all of and only those terms and conditions appearing on the front and back of this document. No additional or substitute terms and/or conditions shall become a part of this contract without the written consent of an officer of Basic Energy Services LP.

SIGNED: *X Rob Long*  
(WELL OWNER, OPERATOR, CONTRACTOR OR AGENT)

ITEM/PRICE REF. NO.	MATERIAL, EQUIPMENT AND SERVICES USED	UNIT	QUANTITY	UNIT PRICE	\$ AMOUNT
E 100	P.u. miles	MI	65		
E 101	Heavy eq. miles	MI	130		
E 113	PROP + Bulk Delivery	TA	595		
CE 204	Depth charge 3001-4000'	YAS	1		
CE 240	Blend + mix charge	SKS	200		
CE 501	CSNY SWIRE 5 1/2	EA	1		
CE 504	plug cont.	EA	1		
S 003	Service Supervisor	EA	1		

SUB TOTAL

CHEMICAL / ACID DATA:			

SERVICE & EQUIPMENT	%TAX ON \$
MATERIALS	%TAX ON \$

TOTAL

SERVICE REPRESENTATIVE: <i>Mike M...</i>	THE ABOVE MATERIAL AND SERVICE ORDERED BY CUSTOMER AND RECEIVED BY: <i>X Rob Long</i>
--	---

FIELD SERVICE ORDER NO. \_\_\_\_\_ (WELL OWNER OPERATOR CONTRACTOR OR AGENT)

Customer **F 9 Holl CO LLC** Lease No. \_\_\_\_\_ Date **12-21-13**  
 Lease **SCOTT CRAW JR 955 TRUSS** Well # **1-25**  
 Field Order # **9571** Station **PRATT** Casing **5 1/2** Depth **3940.78** County **PAWNEE** State **KS**  
 Type Job **CNW L.S.** Formation **TD 3950** Legal Description \_\_\_\_\_

PIPE DATA		PERFORATING DATA		FLUID USED		TREATMENT RESUME		
Casing Size	Tubing Size	Shots/Ft		Acid	RATE	PRESS	ISIP	
<b>5 1/2</b>				<b>125 SKS AA-2</b>	<b>75 SKS AA-2</b>			
Depth <b>3940.78</b>	Depth	From	To	Pre Pad	Max		5 Min.	
Volume <b>96.2</b>	Volume	From	To	Pad	Min		10 Min.	
Max Press <b>1500</b>	Max Press	From	To	Frac	Avg		15 Min.	
Well Connection <b>P.C.</b>	Annulus Vol.	From	To		HHP Used		Annulus Pressure	
Plug Depth <b>3976.22</b>	Packer Depth	From	To	Flush	Gas Volume		Total Load	

Customer Representative **Rob Long** Station Manager **Kevin Gulley** Treater **Mike Matta**  
 Service Units **3758L** **27463** **19831** **19867**  
 Driver Names **Matta** **Kurin** **Jerry**

Time	Casing Pressure	Tubing Pressure	Bbls. Pumped	Rate	Service Log
<b>12:20 PM</b>					<b>ON LOCATION / SAFETY MEETING</b>
<b>12:40</b>					<b>Run 5 1/2 14# CSNG</b>
<b>2:15</b>					<b>CONT ON 1,2,3,4,5,6,7,8 BASKET ON #6</b>
<b>2:30</b>					<b>CSNG ON BOTTOM</b>
<b>4:47</b>	<b>300</b>		<b>5</b>	<b>5</b>	<b>HOOK UP TO CSNG / BREAK CIRC W RIG</b>
<b>4:48</b>	<b>300</b>		<b>12</b>	<b>5</b>	<b>Circ + ROTATE 2 HRS</b>
<b>4:51</b>	<b>300</b>		<b>5</b>	<b>5</b>	<b>PUMP 5 BBL H2O</b>
<b>4:53</b>	<b>300</b>		<b>5</b>	<b>5</b>	<b>PUMP 12 BBL SUPERANUS</b>
<b>4:55</b>	<b>250</b>		<b>37</b>	<b>5</b>	<b>PUMP 5 BBL H2O</b>
<b>5:05</b>					<b>Mix 25 BACKSCAVENGE</b>
<b>5:08</b>					<b>Mix 125 SKS AA-2</b>
<b>5:09</b>	<b>100</b>			<b>5</b>	<b>WASH PUMP + LINE</b>
<b>5:24</b>	<b>500</b>		<b>#85</b>	<b>4</b>	<b>RELEASE PLUG</b>
<b>5:26</b>	<b>900/1400</b>		<b>95</b>		<b>START DISPLACEMENT</b>
<b>5:46</b>			<b>7.5</b>		<b>SLOW RATE / STOP ROTATION</b>
					<b>Plug DOWN PSI TO 1400, RELEASED HEAD</b>
					<b>Plug R.H. + M.H.</b>
					<b>Circ Then JUB</b>
					<b>JUB COMPLETE</b>
					<b>THANK YOU!</b>
					<b>MIKE MATTA</b>