

No. 5060

EXPRESS WELL SERVICE & SUPPLY, INC.

Victoria, Kansas 67671

Company Circle G Date August 15 20 13

Lease Wolfe Well # 1 Co. Doyle KANSAS

Directions Colliger - Hwy 40 - W to 78 Rd - N to AA Rd - E to DE - N to well - Plug

Job Description Cause of Failure No. of Rods or Joints Deep Size and Type of Replacement (new) (used)

WELL RECORD

PULLED FROM WELL

RERAN IN WELL

Feet	Joints	Description	Condition	Equipment	Feet	Joints	Description
16'		1 1/4"		Polish Rod			
6'		1 1/2"		Liner			
		4' x 3/4"		Rod Subs			
	150	3/4"		Rods			
				Rods			
				Rods			
		2 x 1 1/2 x 12'		Pump			
				Tubing Subs			
	121	2 3/8"		Tubing			
				Tubing			
				Bbl. Seat N.			
		Where Set Type Size		Packer or Tubing Anchor			Where Set Type Size
3'		Perf Sub		Mud Anchor			

- Y N Paint _____
- Y N Diesel _____ Gal x _____ = _____
- Thread Dope _____ # _____ each = _____
- Y N Stuff Box Rub _____
- Y N Fishing Tool _____
- Y N Circ Head _____
- Circ Rubber New _____ Used _____
- Y N Packer (type) _____
- Y N Plug _____
- Y N Sand Pump _____
- Y N Swab Equip _____
- Y N Oil Saver Rub _____
- Y N Swab Cups _____

Unit Rig # 2
 Operator Dale W.
 Floorman William
 Floorman Chris Schl

Hrs.	Per Hr.	Amount
8	10400	832.00
8	3800	304.00
8	3400	272.00
8	3400	272.00
EXTRA EQUIP		
SALES TAX		132.72
TOTAL		1812.72

Bad	Replacements
# _____ jts _____	' # _____ jts _____
# _____ rods _____	" # _____ rods _____
Rod Boxes Replaced 3/4" _____ 7/8" _____ 1" _____	

Y N Testing tbg: Who tested: _____

Results: _____

Items used from Express: _____

Items used from other suppliers: _____

No. 5061

EXPRESS WELL SERVICE & SUPPLY, INC.

Victoria, Kansas 67671

Company Circle G Date August 16 20 13
Lease Wolfe Well # 1 Co. KANSAS
Directions _____

Job Description _____ Cause of Failure _____ No. of Rods or Joints Deep _____ Size and Type of Replacement (new) (used) _____

WELL RECORD

PULLED FROM WELL

RERAN IN WELL

Feet	Joints	Description	Condition	Equipment	Feet	Joints	Description
				Polish Rod			
				Liner			
				Rod Subs			
				Rods			
				Rods			
				Rods			
				Pump			
				Tubing Subs			
				Tubing			
				Tubing			
				Bbl. Seat N.			
		Where Set Type Size		Packer or Tubing Anchor			Where Set Type Size
				Mud Anchor			

Y N Paint _____
 Y N Diesel _____ Gal x _____ = _____
 Thread Dope 6 # 4.55 each = \$27.30
 Y N Stuff Box Rub _____
 Y N Fishing Tool _____
 Y N Circ Head _____ \$85.00
 Circ Rubber New _____ Used 23/8 \$10.00
 Y N Packer (type) _____
 Y N Plug _____
 Y N Sand Pump _____
 Y N Swab Equip _____
 Y N Oil Saver Rub _____
 Y N Swab Cups _____

Unit	Hrs.	Per Hr.	Amount
<u>Rig #2</u>	<u>12</u>	<u>10400</u>	<u>1248.00</u>
<u>Operator Dale W.</u>	<u>12</u>	<u>3800</u>	<u>456.00</u>
<u>Floorman Mike D.</u>	<u>12</u>	<u>3400</u>	<u>408.00</u>
<u>Floorman Chris Schl.</u>	<u>12</u>	<u>3400</u>	<u>408.00</u>
			<u>182.30</u>
		EXTRA EQUIP	<u>213.48</u>
		SALES TAX	<u>2915.78</u>
		TOTAL	

Bad	Replacements
# _____ jts _____	' # _____ jts _____
# _____ rods _____	" # _____ rods _____
Rod Boxes Replaced 3/4" _____	7/8" _____ 1" _____

Y N Testing tbg: Who tested: _____

Results: _____

Items used from Express: _____

Items used from other suppliers: _____

KANSAS CORPORATION COMMISSION



Conservation Division
 130 South Market, Suite 2078
 Wichita, Kansas 67202-3801
 316-337-6200
 Fax: 316-337-6211
 FEIN: 48-1124839

INVOICE Customer Copy

6G TWISTER, INC.
 P. O. BOX 1565
 GILLETTE

WY 82717

Invoice Date: October 18, 2013

Invoice Number: 2014060362

Fed ID:

Due Date: November 02, 2013

Order Number: 30158		Contact:		Order Date: October 18, 2013	
Item	Qty	Acct Code / Service Description	Details	Unit Price	Total
1	4692	505 / Well Plugging > 1077 feet	15-063-20729-0000 WOLF T 1 24-11S-26W	\$0.0325	152.49
2	4700	505 / Well Plugging > 1077 feet	15-063-20767-0002 WOLF T 2 24-11S-26W	\$0.0325	152.75
KCC Contact: MARCOTTE, MARJORIE				Order Subtotal:	\$305.24

Order Total: \$305.24
Shipping Charges: 0.00
Invoice Total: \$305.24

IMPORTANT!
 Please Return One Copy of Invoice
 with Your Payment
 in Order to ensure Correct Credit to Your Account.

PAID
 PAID NOV 01 2013
 BY: 1336

RECEIVED
 OCT 24 2013
 BY:

Enterea 10.30.13