



TRILOBITE TESTING INC.

1515 Commerce Parkway • Hays, Kansas 67601

Test Ticket

NO. 51833

4/10

Well Name & No. Bookstore # 3 Test No. 5 Date 12-19-13
 Company Jones Oil LLC. Elevation 1963 KB 1958 GL
 Address 112 N. Gray St. St. John, KS 67576-1923
 Co. Rep / Geo. Keaton Jones / Jeff Burke Rig Petromark # 2
 Location: Sec. 2 Twp. 24s Rge. 14w. Co. Stafford State KS

Interval Tested 3837-3860 Zone Tested Lansing "L"
 Anchor Length 23 Drill Pipe Run 3715 Mud Wt. 9.4
 Top Packer Depth 3832 Drill Collars Run 117 Vis 51
 Bottom Packer Depth 3837 Wt. Pipe Run Ø WL 10.8
 Total Depth 3860 Chlorides 10000 ppm System LCM Ø
 Blow Description IF: Weak blow, surf. - 2" ISI: No blow.
FF: Weak blow, 1/2" - 2 1/2" FSI: No blow.

Rec	Feet of	%gas	%oil	%water	%mud
<u>30</u>	<u>OCM</u>	<u>10</u>		<u>90</u>	
Rec	Feet of	%gas	%oil	%water	%mud
Rec	Feet of	%gas	%oil	%water	%mud
Rec	Feet of	%gas	%oil	%water	%mud
Rec	Feet of	%gas	%oil	%water	%mud

Rec Total 30 BHT 107 Gravity w/c API RW n/c @ n/c °F Chlorides 10000 ppm
 (A) Initial Hydrostatic 1967 Test 1715 T-On Location
 (B) First Initial Flow 18 Jars 1737 T-Started
 (C) First Final Flow 20 Safety Joint 1915 T-Open
 (D) Initial Shut-In 66 Circ Sub 2145 T-Pulled
 (E) Second Initial Flow 21 Hourly Standby 2327 T-Out
 (F) Second Final Flow 25 Mileage _____
 (G) Final Shut-In 96 Sampler _____
 (H) Final Hydrostatic 1885 Straddle _____
 Ruined Shale Packer _____
 Shale Packer _____ Ruined Packer _____
 Extra Packer _____ Extra Copies _____
 Initial Open 30 Extra Recorder _____ Sub Total _____
 Initial Shut-In 45 Day Standby _____ Total _____
 Final Flow 30 Accessibility _____ MP/DST Disc't _____
 Final Shut-In 45 Sub Total _____

Approved By _____ Our Representative Ryan Reynolds
 Trilobite Testing Inc. shall not be liable for damaged of any kind of the property or personnel of the one for whom a test is made, or for any loss suffered or sustained, directly or indirectly, through the use of its equipment, or its statements or opinion concerning the results of any test, tools lost or damaged in the hole shall be paid for at cost by the party for whom the test is made.