

Customer Shelby Resources, LLC	Lease No.	Date 2-27-14
Lease Fonwick	Well # 1-35	
Field Order # 10131	Station Pratt, Kansas	Casing 3 1/2" 14Lb.
		Depth 4014 Feet
Type Job C.N.W. - Long string	Formation	County Pawnee
		State Kansas
		Legal Description 35-215-16W

PIPE DATA		PERFORATING DATA		FLUID USED		TREATMENT RESUME		
Casing Size 3 1/2" 14Lb./ft.	Tubing Size 2 1/8" 9.3Lb./ft.	Shots/Ft 50	sacks/ft 60	Acid 40 Poz Blend	cement for scavenger	RATE	PRESS	ISIP
Depth 4014 Feet	Depth	From 100	To sacks AA2	Pre Pad cement with .58	Fluid Loss	Max	.258	Friction Reducer, 10% Salt,
Volume 48 Bbl.	Volume	From 1.258	To Gas Blk.	Pad .25Lb./stk cellflite,	5Lb./stk. Gilsonite	Min		10 Min.
Max Press 1500 P.S.I.	Max Press	From	To	Frac 15.3Lb./Gal.	Avg 44 Gal./stk., 1.36			15 Min.
Well Connection Plug on Lainer	Annulus Vol.	From 50	To Additional sacks	60/40 Poz to Plug Rat	(30 sacks) and	HHP Used		Annulus Pressure
Plug Depth 3495 Feet	Packer Depth	From	To	Flush 97.4 Bbl. Fresh Water	Gas Volume			Total Load

Customer Representative Chris Gotschalt	Station Manager Kevin Gordley	Treater Clarence R. Messick
--	----------------------------------	--------------------------------

Service Units	37216	19889	19843	19831	19862				
Driver Names	Messick	Masquez	Hamby						

Time P.M.	Casing Pressure	Tubing Pressure	Bbls. Pumped	Rate	Service Log
10:00					Trucks on location and hold safety meeting.
12:00					Steering Drilling start to run Auto Fill Float Shoe. Shoe Joint with Latch Down Baffle screwed into collar and a total of 96 Joints now 14Lb/Ft. 5 1/2" casing. A Basket was installed on top of Guide Shoe. A Turbolizer was installed on collars #2, 3, 5 and #6.
2:30					Casing in well. Circulate for 1 hour.
3:33		2,000			Shut in well. Pressure Test. Open Well.
3:37	400			5	Start mixing 50 sacks 60/40 Poz for scavenger.
	400		10	5	Start mixing 100 sacks AA2 Blend cement.
			34		Stop pumping. Shut in well. Wash pump and lines. Release Latch Down Plug. Open Well.
3:48	150			6.5	Start Fresh Water Displacement.
			78	4	Start to lift cement.
4:05	800		97.4		Plug down.
	1,500				Pressure up.
					Release pressure. Float Shoe hold.
			7-5	3	Plug Rat and Mouse holes.
					Wash up pump truck.
5:00					Job Complete.
					Thank You.
					Clarence, Edmund, Terry