

Approximate section links were determined using the normal standard of care of pilfield surveyors practicing in the state of Kansas. The section corners, which establish the precise section lines, were not necessarily located, and the exact location of the drillsite location in the section is not guaranteed. Therefore, the operator securing this service and accepting this plat and all other parties relying thereon agree to hold Central Kansas Diffield Services, Inc., its officers and employees harmless from all losses, costs and expenses and said entities released from any liability from incidental or cansequential damages

vn on thi. Iegolly

De le

201 ion

per

Ingress plat is opened t

Ingr 0 l at

for access.

March 26, 2014

Date

CENTRAL KANSAS OILFIELD SERVICES, INC. (620)792-1977