

NO ROAD

to location as shown on this nnly and may not be legally se. Contact landowner. oad department for access.

## Notes:

- 1. Set iron rod at location site.
- 2. All flagging Red & Yellow.
- 3. No overhead power available at Sec. 19.
- 4. Kansas One Call System Inc. should be notified before excavation (1-800-344-7233).
- 5. CAUTION; Various pipelines in Sec. 19.
- 6. Section 19 is irregular.
- 7. Contact landowner for best access.
- 8. Original location (1480'FSL 850'FWL) fell on the slope of a draw, set new location footages per representative.





<sup>\*</sup> Controlling data is based upon the best maps and photographs available to us and upon a regular section of land containing 640 ocres.

Elevations derived from National Geodetic Vertical Datum

June 19, 2014

<sup>\*</sup>Approximate section lines were determined using the normal standard of care of oilfield surveyors practicing in the state of Kansas. The section carners, which establish the precise section lines, were not necessarily located, and the exact location of the drillsite location in the section is not guaranteed. Therefore, the operator securing this service and accepting this plot and all other parties relying thereon agree to hold Central Kansas Dilfield Services. Inc. its officers and employees formless from all losses, costs and expenses and said entities released from any liability from incledantal or consequential damages.