

JOB LOG

SWIFT Services, Inc.

DATE 9-10-14 PAGE NO. 1

CUSTOMER *T D I* WELL NO. # *2* LEASE *Zimmerman Unit* JOB TYPE *Deep Surface* TICKET NO. *26767*

CHART NO.	TIME	RATE (BPM)	VOLUME (BBL) (GAL)	PUMPS		PRESSURE (PSI)		DESCRIPTION OF OPERATION AND MATERIALS
				T	C	TUBING	CASING	
	1100							<i>on loc w/ FE</i>
								<i>RTD</i>
								<i>8 5/8" x 23 # x</i>
								<i>Cent 1, 3, 14</i>
	1300							<i>start FE</i>
	1515							<i>Break Line</i>
	1540	5	0				200	<i>start 500gal Mud flush</i>
	1542	5	12/0				200	<i>start 20 bbl KCL flush</i>
	1546	5	20/0				200	<i>start 125 sks SMD @ 11.8 #</i>
	1557	5	57/0				200	<i>start 100 sks SMD @ 12.5 #</i>
	1605	5	38/0				200	<i>start 75 sks SMD @ 13.5 #</i>
	1609	5	23/0				200	<i>start 75 sks SMD @ 14.5 #</i>
	1613		20					<i>End Cement</i>
								<i>Drop Plug</i>
	1617	5	0				200	<i>start Displacement</i>
	1623	4	30				300	<i>Circ. Cement</i>
	1635		73.5				500/500	<i>Land Plug</i>
								<i>Shut in</i>
								<i>circ 75 sks topit</i>
								<i>Thank you</i>
								<i>Nick, David E., Austin & Preston</i>

JOB LOG

SWIFT Services, Inc.

DATE 9-15-14 PAGE NO. 7

CUSTOMER TDF WELL NO. #2 LEASE Zimmerman Unit JOB TYPE Longstring TICKET NO. 26769

CHART NO.	TIME	RATE (BPM)	VOLUME (BBL) (GAL)	PUMPS		PRESSURE (PSI)		DESCRIPTION OF OPERATION AND MATERIALS
				T	C	TUBING	CASING	
	0900							on loc w/FE
								RTD 3760 LTD 3756 5 1/2" x 14.0" # 3753' x 42' Centralizers 1, 3, 9, 6, 8, 10, 12, 13, 15 Baskets 4, 9
	1030							Start F.E.
	1150							Break Circ.
	1255	2	7/4					Plug RH+MH 30/15 sks EA-2
	1305	5	0			200		Start 500gal Mud Plush
	1310	5	12/0			200		Start 20bbl KCL Plush
	1310	5	20/0			200		Start 125sks EA-2 cement
	1315		32					End Cement Wash P&L Drop D Plug
	1325	6	0			200		Start Displacement
	1335	5	64			250		Catch Cement
	1340		90.5			700/ 1300		Land Plug Release Pressure Float Held
Thank you								
Nick, David E. Austin, & Isaac								