

QUALITY WELL SERVICE, INC.

6158

Federal Tax I.D. # 481187368

Home Office 324 Simpson St., Pratt, KS 67124

Office 620-727-3410
Fax 620-672-3663

Rich's Cell 620-727-3409
Brady's Cell 620-727-6964

Date	07-08-14	Sec.	32	Twp.	29S	Range	24W	County	Ford	State	KS	On Location	12 noon	Finish	2:00 PM	
Lease	Marfam		Well No.		3-32		Location									Bloom, KS, 3 1/2 w. of int
Contractor	Duke #1							Owner								Vincent
Type Job	Surface							To Quality Well Service, Inc.								You are hereby requested to rent cementing equipment and furnish cementer and helper to assist owner or contractor to do work as listed.
Hole Size	12 1/4		T.D. 649'													
Csg.	8 5/8		Depth 649'													
Tbg. Size			Depth													
Tool			Street													
Cement Left in Csg.	42'		Shoe Joint		42.15		The above was done to satisfaction and supervision of owner agent or contractor.									
Meas Line			Displace		29 BBls Fresh		Cement Amount Ordered								125sx MDC + 1/4" Flowseal &	
EQUIPMENT							125sx class A + 3%cc + 2%gel + 1/4" Flowseal									
Pumptrk	8	No.	David F				Common								125	
Bulktrk	10	No.	David B				Rez. MIX								MDC 125	
Bulktrk	7	No.	Mike B				Gel.								11	
Pickup		No.					Calcium								10	
JOB SERVICES & REMARKS							Hulls									
Rat Hole			Salt													
Mouse Hole			Flowseal													66.25
Centralizers			Kol-Seal													
Baskets			Mud CLR 48													
D/V or Port Collar	Rev 15. its		8 5/8 csg		CFL-117 or CD110 CAF 38											
Pipe on BHM, Break Circ., Pump Spacer			Sand													
Mix Light Weight Cement, Mix tail Cement			Handling													271
Stop Pump, Release Plug, Start Disp			Fresh H ₂ O, Wash up on Plug, See Steady													
increase in PSI, Slow Rate,			Mileage													50
Bump Plug at 29 BBls total Disp,			FLOAT EQUIPMENT													
Shooting Cement Did Circ.			Guide Shoe													
			Centralizer													
			Baskets													
			AFU Inserts - Baffle Plate													
			Float Shoe													
			Latched Down Service Supervisor													
			Wooden Cap Plug													
			LMV 50													
			Pumptrk Charge													Surface
			Mileage													50 x 2
													Tax			
													Discount			
													Total Charge			
X Signature <i>Mike Stahly</i>																

QUALITY WELL SERVICE, INC.

6189

Federal Tax I.D. # 481187368

Home Office 324 Simpson St., Pratt, KS 67124

Office 620-727-3410
Fax 620-672-3663

Rich's Cell 620-727-3409
Brady's Cell 620-727-6964

Date	07-19-14	Sec.	32	Twp.	29s	Range	24w	County	Ford	State	KS	On Location	9:00 AM	Finish	2:00 PM	
Lease	MarFam	Well No.	3-32			Location Bloom, KS, 3 1/2 mi s/into										
Contractor	Duke #1							Owner	Vincent							
Type Job	Rotary Plug TA							To Quality Well Service, Inc. You are hereby requested to rent cementing equipment and furnish cementer and helper to assist owner or contractor to do work as listed.								
Hole Size	7 7/8		T.D.		5467'		Charge To Vincent									
Csg.	8 5/8		Depth		648'		Street									
Tbg. Size	4 1/2 Drill Pipe		Depth		1590'		City State									
Tool			Depth				The above was done to satisfaction and supervision of owner agent or contractor.									
Cement Left in Csg.			Shoe Joint				Cement Amount Ordered 170sx 60:40:4%gel + 14CF									
Meas Line			Displace		Fresh H ₂ O											

EQUIPMENT

Pumptrk	8	No.	David B.	Common	105
Bulktrk	7	No.	David F.	Poz. Mix	65
Bulktrk		No.		Gel.	6
Pickup		No.		Calcium	

JOB SERVICES & REMARKS

Rat Hole	30sx	Hulls	
Mouse Hole	20sx	Salt	
Centralizers		Flowseal	42.50
Baskets		Kol-Seal	
D/V or Port Collar		Mud CLR 48	
Drill Pipe at 1590' Load hole, Pump		CFL-117 or CD110 CAF 38	
Fresh Spacers, Mix 50sx cement, 0!sp.w/		Sand	
19 BBLs water,		Handling	176
		Mileage	50

FLOAT EQUIPMENT

Drill Pipe at 680' Load hole, Pump	Guide Shoe
Spacer, Mix 50sx, Disp. w/ 6 1/2 BBLs water	Centralizer
Pipe at 60' Load hole, mix 20sx	Baskets
Cement Did Line,	AFU Inserts
Plug Rat & Mouseholes w/ 50sx	Float Shoe
	Latch Down
	LMV 50
	Service Supervisor
	Pumptrk Charge 14-Rotary Plug
	Mileage 50 x 2

Signature	Mike Rodkey	Tax
		Discount
		Total Charge