

JOB LOG

SWIFT Services, Inc.

DATE 11-26-14 PAGE NO. 1

CUSTOMER TDI WELL NO. #2 LEASE Charlotte JOB TYPE Cement Surface Casing TICKET NO. 26975

CHART NO.	TIME	RATE (BPM)	VOLUME (BBL) (GAL)	PUMPS		PRESSURE (PSI)		TD 1170'	DESCRIPTION OF OPERATION AND MATERIALS
				T	C	TUBING	CASING		
	1100								On location - Float Equip start casing - 8 5/8" - 23 #/ft. to 1168' ST 34 1/2' - Baffle Plate 11.37.63' = 72 1/4 (881) Cont 1-3-14
	1900								Fin run casing
	1915								St. CIR - Wait on last ticks
	2000								Fin CIR
	2005	5	12				300		500 gal Mud Flush
		6	20				300		20 BBL KCL Flush
		5	59				300		125 SKS @ 11.8 #/gal
		5	38	97			300		100 SKS @ 12.5 #/gal
		4 1/2	23	120			300		75 SKS @ 13.5 #/gal
		4	20	140			300		75 SKS @ 14.5 #/gal
							Var		Fin cont
									Release Plug
		6					300		Start Displ
		5	15				500		Cont circulating to Pit 75/sks
	2115		72 1/4				600 900		Plug Down - close in
									Washup P.T & Reelup
									Job Complete
									Thanks Don, Jon, Steve Jared & Tyler

JOB LOG

SWIFT Services, Inc.

DATE 12-1-14 PAGE NO.

CUSTOMER TDI WELL NO. #2-Twin LEASE Charlotte Trust JOB TYPE Cement Logging TICKET NO. 27102

CHART NO.	TIME	RATE (BPM)	VOLUME (BBL) (GAL)	PUMPS		PRESSURE (PSI)		TD	DESCRIPTION OF OPERATION AND MATERIALS
				T	C	TUBING	CASING		
12/1	2145							3650	DN location - Float Equip
	2215								start 5 1/2" 14 #ft Casings to 3649"
									Insert Float Shoe (w) / Fill-up
									L.D. Baffle - 55 - 43 1/2' @ 3605 1/2' (88) 881
									Coat 1-3-5-7-9-11-13-15
									Cement Basket #2
									Drop fill-up ball & JTs out
	2350								Fin run casing - Tag & lay it. Down
	2400								Start air / Rotate
12/2	0100								Fin air - wtc fits here
									Plug RH - 30 SKS MH - 20 SK std cut
		5						300	500 gal Mead Flush
		6						350	20 BBL KCL Flush
		4 1/2						300	Start 125 SKS EH-2 cut
								vac	Fin cut
									Wash out pump & lines
		9						700	Drop L.D. Plug
		9	65					500	Start Displ
		7 1/2	75					700	Caught left
		6	80					700	slow rate
		5 1/2	85					800	slow rate
		5 1/2	87					850	last air press
	0150	0	88					1500	Plug Down - Held - Release & Held
									Job Complete
	0200								Wash up & Rack up Trks
	0230								Thanks Hon - Jon - Steve & Craig