OPERATOR

Company: LIBERTY OPERATIONS _COMPLETIONS INC.

Address: 100 SW 9TH

PLAINVILLE, KANSAS 67663-2229

Contact Geologist: ROGER COMEAU
Contact Phone Nbr: 785-434-4686
Well Name: LINDSEY # 1

ell Name: LINDSEY # 1
Location: SE SW SE

API: 15-163-00367-00-01

Pool: Field: WEBSTER VIEW

State: KANSAS Country: USA

Scale 1:240 Imperial

Well Name: LINDSEY # 1
Surface Location: SE SW SE

Bottom Location:

API: 15-163-00367-00-01

License Number: 8925 Spud Date: 8/29/2

8/29/2015 Time: 2:00 AM

Region: ROOKS COUNTY

Drilling Completed: 8/30/2015 Time: 9:48 AM

Surface Coordinates: 330' FSL & 1350' FEL

Bottom Hole Coordinates:

Ground Elevation: 1922.00ft K.B. Elevation: 1927.00ft

Logged Interval: 2700.00ft To: 3566.00ft

Total Depth: 3510.00ft Formation: ARBUCKLE

Drilling Fluid Type: CHEMICAL/FRESH WATER GEL

SURFACE CO-ORDINATES

Well Type: Vertical
Longitude: -99.3844706
Latitude: 39.3948965
N/S Co-ord: 330' FSL
E/W Co-ord: 1350' FEL

LOGGED BY



Company: SOLUTIONS CONSULTING, INC.

Address: 108 W 35TH

HAYS, KS 67601

Phone Nbr: (785) 639-1337

Logged By: GEOLOGIST Name: HERB DEINES

CONTRACTOR

Contractor: WHITE KNIGHT DRILLING LLC

Rig #: 1

Rig Type: MUD ROTARY

 Spud Date:
 8/29/2015
 Time:
 2:00 AM

 TD Date:
 8/30/2015
 Time:
 9:48 AM

 Rig Release:
 8/31/2015
 Time:
 9:00 AM

ELEVATIONS

K.B. Elevation: 1927.00ft Ground Elevation: 1922.00ft

K.B. to Ground: 5.00ft

NOTES

THE LINDSEY # 1 WAS A REENTRY OF AN OLD DRY AND ABANDONED WELL DRILLED IN 1950. THE WELL WAS

REENTERED AND WASHED DOWN TO THE LKC WHERE AN OUT OF GAUGE HOLE WAS ENCOUNTERED WHICH REQUIRED SOME REAMING. THE CONDITION AND WEAR PATTERN ON THE BIT CONFIRMED SUSPICIONS. ONCE IT WAS DETERMINED THAT THE HOLE WAS CLEAN TO THE OLD ROTARY TOTAL DEPTH, THE OLD STARCH MUD WAS DISPLACED WITH A FRESH CHEMICAL MUD SYSTEM TO ALLOW GOOD LOGS TO BE RAN AND POSSIBLE TESTING. AFTER DISPLACEMENT SOME ARTESIAN FLOW WAS NOTED AT THE FLOW LINE WHICH WAS CONTROLLED BY INCREASING THE MUD WEIGHT. DECISION TO RUN CASING BASED ON FAVORABLE STRUCTURE, LOG ANALYSIS AND UNFAVORABLE HOLE CONDITIONS WHICH MADE FURTHER TESTING RISKY.


OPEN HOLE LOGGING BY GEMINI WIRELINE: DUAL INDUCTION LOG, COMPENSATED DENSITY NEUTRON LOG, MICRO RESISTIVITY LOG AND BOREHOLE COMPENSATED SONIC LOG


NO DRILL STEM TESTS WERE RAN ON THE WELL.

	LINDSEY # 1 SE SW SE SEC.36-7S-19W 1922'GL 1927'KB	HILGERS B-1 NW NW NE SEC.1-8-19W KB 1940'	FARR # 2 SW NW NE NE SEC.1-8-19W KB 1930'
FORMATION	LOG TOPS	LOG TOPS	LOG TOPS
Anhydrite	1363 +564	+ 565	+ 575
B-Anhydrite	1398 +529	+ 530	+ 538
Topeka	2858- 931	- 936	- 936
Heebner Sh	. 3063-1136	-1142	-1144
LKC	3102-1175	-1182	-1180
ВКС	3323-1396	-1406	-1406
Arbuckle	3407-1480	-1470	-1486
RTD	3566-1639	-1545	-1585


SUMMARY OF DAILY ACTIVITY

8-28-15	Move and rig up mud rotary rig
8-29-15	Spud 2:00 AM, drill cement plug, wash down to OTD with old starch
	mud in hole
8-30-15	3510', displaced old mud system with chemical mud system, RTD
	3566' @9:48AM, mini short trip, CCH, TOWB, slope survey 1 degree
	@ 3566', logs-DIL-CDNL-MEL-BCS, TIWB, CCH, LDDP
8-31-15	3566', run production casing and cement bottom and top stages, RD





						-			
	+					Ŧ			
				+		2780			
						<u> </u>			
						ł			
	+			+		2790			
						‡			
						ţ			
0	+	ROP (i	min/ft)	6	2800			
	+			+		F			
						‡			
						2810			
						Ł			
	-			-		F			
						2820			
						ţ			
						1			
	F					2830			
	+					Ŧ			
	#					2840			
	\perp					±			
	+		H			+			
	Ŧ			+		2850			
	#					‡			
	\pm					t		TOPEKA 2858-931	
	+					2860		101 2134 2000 001	
	\perp					‡			
						‡			
	+					2870			
	+					F			
	+			\perp		Ŧ			
	†					2880			
						Ė			
	-			+		F			
						2890			
						‡			
						2900			
	+			+		12300			
	-					F			
	+			+		2910			
	#					‡			
	\pm					†			
	+					2920			
	Ŧ					F			
	+			+		F			
				+		2930			
	\pm					t			
	\pm			\pm		2040			
						2940			
	#					‡			
	$^{+}$					2950			
	\pm					± 555			
	+		H			+	<u> </u>		
	\dotplus			+		2960			
	#					‡			
	\pm					t			
	F				+	2970			
	+					Ŧ			
	#					‡			
	\pm					2980			
	+					ł			
	\mp					F_			
\perp	\pm					2990			



3220 3230 LOG INTERVAL 3235 TO 3238 SHOULD BE PERFORATED AND TESTED PRIOR TO 3240 ABANDONMENT OF WELL 3250 3260 DST # 2 3270' TO 3278' **OPEN 30 MINUTES** WEAK BLOW FOR 2 MINUTES **RECOVERED 5' DRILLING** 3270 MUD B.H.P. 976# 3280 LOG INTERVAL 3274 TO 3280 SHOULD BE PERFORATED AND TESTED PRIOR TO ABANDONMENT OF WELL. 3290 **EVEN THOUGH THE ZONE** WAS TESTED, THE BHP PRESSURE OF 975# WAS GOOD. MICROLOG SHOWS 3300 SOME PERMEABILITY **ALBEIT THINLY DEVELOPED** Κ 3310 3320 BKC 3323-1396 3330 3340 3350 3360 3370 3380 3390 3400 ROP (min/ft) **ARBUCKLE 3407-1480** 3410 3420 LOG INTERVAL 3436 TO 3443 SHOULD BE PERFORATED AND TESTED. THIS ZONE 3430

