



# TRILOBITE TESTING INC.

1515 Commerce Parkway • Hays, Kansas 67601

## Test Ticket

NO. 60591

4/10

Well Name & No. Saindon 1-33 Test No. 1 Date 6-26-15  
 Company AMERICAN OIL LLC Elevation 2205 KB 2197 GL  
 Address 1023 RESERVATION RD. HAYS, KS 67601  
 Co. Rep / Geo. AUSTIN KLAUS, ZACH PATTERSON Rig DISCOVERY RIG 1  
 Location: Sec. 33 Twp. 9<sup>s</sup> Rge. 19<sup>w</sup> Co. Rooks State Ks

Interval Tested 3477-3503 Zone Tested 1KC  
 Anchor Length 26 Drill Pipe Run 3444 Mud Wt. 9  
 Top Packer Depth 3472 Drill Collars Run 30 Vis 53  
 Bottom Packer Depth 3477 Wt. Pipe Run - WL 7.2  
 Total Depth 3503 Chlorides 3000 ppm System LCM 1 1/2 #  
 Blow Description TFP - WEAK TO STRONG IN 4 MIN  
TSIP - NO BLOW  
FFP - WEAK TO STRONG IN 9 MIN  
FSIP - NO BLOW

Rec	Feet of	%gas	%oil	%water	%mud
<u>765</u>	<u>WATER</u>				
Rec	Feet of	%gas	%oil	%water	%mud
Rec	Feet of	%gas	%oil	%water	%mud
Rec	Feet of	%gas	%oil	%water	%mud
Rec	Feet of	%gas	%oil	%water	%mud

Rec Total 765 BHT 108 Gravity - API RW .2 @ 54 ° F Chlorides 54000 ppm

(A) Initial Hydrostatic 1665  Test 2310  
 (B) First Initial Flow 41  Jars 0005  
 (C) First Final Flow 249  Safety Joint 0220  
 (D) Initial Shut-In 642  Circ Sub 0450  
 (E) Second Initial Flow 265  Hourly Standby 0651  
 (F) Second Final Flow 389  Mileage 70 RT  
 (G) Final Shut-In 645  Sampler  
 (H) Final Hydrostatic 1646  Straddle  Ruined Shale Packer  
 Shale Packer  Ruined Packer  
 Extra Packer  Extra Copies  
 Extra Recorder  
 Day Standby  
 Accessibility

Initial Open 30  
 Initial Shut-In 30  
 Final Flow 30  
 Final Shut-In 60

Sub Total \_\_\_\_\_  
 Total \_\_\_\_\_  
 MP/DST Disc't \_\_\_\_\_

Approved By \_\_\_\_\_ Our Representative RAY SCHWAGER Thank you

TriLOBITE TESTING Inc. shall not be liable for damaged of any kind of the property or personnel of the one for whom a test is made, or for any loss suffered or sustained, directly or indirectly, through the use of its equipment, or its statements or opinion concerning the results of any test, tools lost or damaged in the hole shall be paid for at cost by the party for whom the test is made.