

CUSTOMER		WELL NO.		LEASE		JOB TYPE		TICKET NO.	
Viking		1-16		Breit		Plug to Abandon		28958	
CHART NO.	TIME	RATE (BPM)	VOLUME (BBL) (GAL)	PUMPS		PRESSURE (PSI)		DESCRIPTION OF OPERATION AND MATERIALS	
				T	C	TUBING	CASING		
								200sk 60/40 pozmix (4% gel) 12sk Bentanite gel 2 3/8 x 1/2 pipe to 4402'	
	1000							on loc TPK 114	
	1015	3 1/2	36					mix gel - 6sk neat 6sk - w/ 100# holls	
		3 1/2	8					mix 60/40 poz (4%) @ 13.1 ppq 30sk w/ 100# holls	
		3 1/2	13					Displace w/ 13bbl H2O	
	1038							pull to 2100'	
	1145	4						pump 20bbl H2O catch 100psi	
		4	20			100		mix 60/40 (4%) @ 13.1 ppq	
		4	14			100		fluid to surface	
		4	39			300		— cement to surface 150sk	
		4				600			
	1202							pull tubing out of hole	
	1300							Pump down 8 1/2 holding pressure 55sk	
						100		top off 4 1/2	
								mix 60/40 poz (4%) 15sk did not fill up 4 1/2	
								— will come back another day - est. 30' to fluid	
	1325							Add 35sk to tight face top off unleak	
	1415							Make up Job complete	
								Plunks Blis Plot & more	