

KANSAS CORPORATION COMMISSION OIL & GAS CONSERVATION DIVISION 1296802

Form CDP-1 May 2010 Form must be Typed

## **APPLICATION FOR SURFACE PIT**

Submit in Duplicate

Operator Name:			License Number:
Operator Address:			
Contact Person:			Phone Number:
Lease Name & Well No.:			Pit Location (QQQQ):
	Artificial Liner?		
If the pit is lined give a brief description of the lin material, thickness and installation procedure.		liner integrity, in	dures for periodic maintenance and determining ncluding any special monitoring.
feet Depth of water wellfeet		Source of inforr	mation:
Image: Index Settling and Burn Pits ONLY:   Producing Formation:   Number of producing wells on lease:   Barrels of fluid produced daily:   Does the slope from the tank battery allow all spilled fluids to flow into the pit?   Yes   No		Drilling, Workover and Haul-Off Pits ONLY:   Type of material utilized in drilling/workover:   Number of working pits to be utilized:   Abandonment procedure:   Drill pits must be closed within 365 days of spud date.	
Date Received: Permit Numl	ber:	Permi	Liner Steel Pit RFAC RFAS

Mail to: KCC - Conservation Division, 130 S. Market - Room 2078, Wichita, Kansas 67202

Conservation Division 266 N. Main St., Ste. 220 Wichita, KS 67202-1513



Phone: 316-337-6200 Fax: 316-337-6211 http://kcc.ks.gov/

Jay Scott Emler, Chairman Shari Feist Albrecht, Commissioner Pat Apple, Commissioner Sam Brownback, Governor

March 15, 2016

Jerry Green Castle Resources, Inc. BOX 87 SCHOENCHEN, KS 67667-0087

Re: Workover Pit Application OSCAR SMITH 2 Sec.02-31S-07W Harper County, Kansas

Dear Jerry Green:

District staff has inspected the location and has determined that an unsealed condition will present a pollution threat to water resources.

District staff has recommended that the Workover pit be lined. If a plastic liner is to be used it must have a minimum thickness of 10 mil. Integrity of the liner must be maintained at all times.

## NO completion fluids or non-exempt wastes shall be placed in the Workover pit.

The free fluids in the Workover pit should be removed as soon as practical after drilling operations have ceased. The fluids should be taken to an authorized disposal well. Please call the District Office at (316) 630-4000 when the fluids have been removed. Please file form CDP-5 (August 2008), Exploration and Production Waste Transfer, through KOLAR within 30 days of fluid removal.

If you have any questions or concerns please feel free to contact the District Office at (316) 630-4000.