



CONSOLIDATED
Oil Well Services, LLC

TICKET NUMBER 50306
LOCATION Ottawa KS
FOREMAN Fred Maden

PO Box 884, Chanute, KS 66720
620-431-9210 or 800-467-8676

FIELD TICKET & TREATMENT REPORT
CEMENT

DATE	CUSTOMER #	WELL NAME & NUMBER	SECTION	TOWNSHIP	RANGE	COUNTY
9-22-16	3602	Gillespie # I-9	NW 31	14	22	JO
CUSTOMER Hoehn Oil LLC			TRUCK #			
MAILING ADDRESS 40971 W 247 th			DRIVER			
CITY Wellsville			TRUCK #			
STATE KS			DRIVER			
ZIP CODE 66092			TRUCK #			
			DRIVER			

JOB TYPE Log string HOLE SIZE 5 7/8 HOLE DEPTH 995 CASING SIZE & WEIGHT 2 7/8 EUE
CASING DEPT 990 DRILL PIPE Buffloin TUBING @ 9 5/8 OTHER _____
SLURRY WEIGHT _____ SLURRY VOL _____ WATER gal/sk _____ CEMENT LEFT in CASING 6' Plug
DISPLACEMENT 5.72 BBL DISPLACEMENT PSI _____ MIX PSI _____ RATE 4+ BPM

REMARKS: Hold Safety meeting. Unable to establish circulation. Initially
MIT. 900' Bentonite Gel w/ 120# Cottonseed hulls to condition
hole. Follow w/ 200 SKS Pop Blend I A Cement 22 Gal
Pheno Seal/sk. w/ 20# Cottonseed hulls. Gained circulation
end of cementing procedure. Flush pump lines clean. Displace
2 1/2" Rubber plug to Baffle in casing. Pressure to 800# PSI.
Monitor Pressure for 30 min MIT. Release pressure to
set float valve.

Fred Maden

ACCOUNT CODE	QUANTITY or UNITS	DESCRIPTION of SERVICES or PRODUCT	UNIT PRICE	TOTAL
CE0450	1	PUMP CHARGE	467	1500 ⁰⁰
CE0002	30 mi	MILEAGE	467	2145 ⁰⁰
CE0211	Minimum	Ten Miles	503	660 ⁰⁰
WE0853	3 hrs	50 BBL Van Truck	675	300 ⁰⁰
		Sub Total		2674 ³⁰
		less 52%		1390 ⁷⁴
CC5842	200 SKS	Pop Blend I A Cement		2700 ⁰⁰
CC5965	2236#	Bentonite Gel		670 ⁸⁰
CC6080	140#	Cottonseed hulls		70 ⁰⁰
CC6079	200#	Pheno Seal		270 ⁰⁰
CP8176	1	2 1/2" Rubber Plug		45 ⁰⁰
		Sub Total		3755 ⁸⁰
		less 52%		1953 ⁰²
			7.725%	SALES TAX
				139 ²⁶
				ESTIMATED TOTAL
				3225 ⁸⁰
				DATE <u>672044</u>

Ravin 3737

AUTHORIZATION Jim Hoehn TITLE Pres DATE _____

I acknowledge that the payment terms, unless specifically amended in writing on the front of the form or in the customer's account records, at our office, and conditions of service on the back of this form are in effect for services identified on this form.