Leis Oil Services, LLC

1410 150th Rd Yates Center, KS 66783

Invoice

Date	Invoice #
4/2/2017	1154

Bill To

Petroluem Resources Management Co.
733 Highgrove Park
Houston, TX 77057

P.O. No.	Terms	Project
	Due on receipt	

Quantity	Description		Rate		Amount
	2-24-17 Pulling Unit #66 broken threads 37th joint. 1 New join			55.00	146.25
3.25	3-1-17 Pulling Unit #5 hole in 17th joint, bad threads on 39th,			55.00	211.25
	joints and pump. #67, rigged up, stroked, fluid was right there, put	on jack, wouldn'			
	pump on jack, left rigged up for next morning.				
7.75	3-2-17 Pulling Unit #67, pump was stuck, couldn't get to come		(55.00	503.7
	bottom, laid unit over and double lined, broke threads at 12th joint		,		
	unseated. Pulled out, went in with tapered tap, screwed in and laid				
	again, worked it out of sand, laid over and took double line off, pu				
	joints and pump. #5, stroked couldn't get it to pump, hit fluid at 13	, tested below and	13		
2	joints above, went to pump and switched out. 3-8-17 Pulling Unit #21, cracked thread 35th joint, 1 joint reall	rotton had to go	to	55.00	195.0
3	Piqua to get pump, replaced pump and 2 joints.	y rotten, nad to go	10	53.00	193.0
1	Drill pit for HMD W 12-17		14	50.00	150.0
12	Cement for surface			2.00	144.0
	Drilling for HMD W 12-17		<u>'</u>	5.25	7,570.5
1,442	Bit charge for Mississippi drilling		80	00.00	800.0
2	Backhoe time to pull Cornish in and out to open hole log			15.00	90.0
	Rig time to run pipe in and wash through a couple of bridges get to	bottom to plug w		50.00	450.0
J	50' plug in Mississippi, gel spacer, 50' plug in Squirrel, gel spacer,				
	City, gel spacer, 300' to surface. Dug down along surface and cut j				
	ground level to not interfere with future farming.	F			
2.5	3-15-16 Pulling Unit #6 bad threads bottom 4 joints, fluid leaki	ng past pump. 4		55.00	162.5
	new joints and new pump.				
5.75	3-21-17 Pulling Unit #24 hole in 36th joint, many other bad thr	eads, 8 new joints	(55.00	373.7
	and pump swap. #15 hole in 26th joint, 1 new joint. #42 laid out of	on barrels for upp	er		
	perf/frac. #21 laid out on barrels for upper perf/frac.				
5.5	3-27-17 Pulling Unit #6 pulled to really, really thick golden flu		h e	55.00	357.5
	16 joints. Decided to wash, had to use pump to push mud out of pi				
	them in. Ran pipe in, washed down the last 14 to brake up mud in				
	to bottom, used soap to help clean pipe, spotted 12.5 gallons of aci	d to try opening w	rell		
	up, left acid to work.				
	3-27-17 Wash Pump wash job for mud on #6.			0.00	250.0
1	3-27-17 Vac Truck vac truck for water for wash job.			75.00	75.0
	<u> </u>				
			Total		

Leis Oil Services, LLC

1410 150th Rd Yates Center, KS 66783

Invoice

Date	Invoice #
4/2/2017	1154

Bill To

Petroluem Resources Management Co.
733 Highgrove Park
Houston, TX 77057

P.O. No.	Terms	Project
	Due on receipt	

P	Description 3-28-17 Pulling unit Washed #6 out again after acid ha		Rate		Amount
P					, anount
1 3 7.5 3 7.5 3 v w w w w w w w w w w w w w w w w w w	Pulled pipe and ran in new pump and 4 new joints. Move washed, retrieved standing valve, ran back in, washed 30' out, ran in 43 joints, new pump, cut and threaded new top up. 3-28-17 Wash pump wash pump for #21. 3-28-17 Vac Truck vac truck for #21. 3-30-17 Pulling unit #42, ran pipe in open, washed up valve, threads got messed up, ran back in with tapered tap we were still clean, screwed in with tap, retrieved standing washed out 25' of sand out of lower, pulled out, ran in pip 3-30-17 Wash Pump wash pump for #42 wash job. 3-31-17 Vac Truck vac truck for #42 wash job. 3-31-17 Pulling Unit #8 pulled pipe, ran back in open, out of bottom. Pulled out, ran back in with new pump, cu 3-31-17 Wash Pump wash pump for #8 wash job. 3-31-17 Vac Truck vac truck for #8 wash job. 3-31-17 Paint- paint and diesel fuel mixed to paint all pweek.	d to #21, ran in pipe ope of sand out of lower, pul piece, moved to #42 and per, tried retrieving stand, washed a little to make a valve, ran in to lower, e, pump with 3 new joint washed only about 2' of t and threaded new top joint washed only about 2' of t and threaded new top joint washed only about 2' of the property of the prop	ling sure ts.	65.00 250.00 75.00 65.00 250.00 75.00 65.00 250.00 75.00 10.00	250.00 75.00 487.50 250.00 75.00 341.25 250.00 75.00 10.00
			Total		\$13,862.00