



**BASIC**<sup>SM</sup>  
ENERGY SERVICES  
PRESSURE PUMPING & WIRELINE

10244 NE Hwy. 61  
P.O. Box 8613  
Pratt, Kansas 67124  
Phone 620-672-1201

FIELD SERVICE TICKET

1718 15244 A

MMH-36

DATE \_\_\_\_\_ TICKET NO. \_\_\_\_\_

DATE OF JOB: 8/8/17		DISTRICT		NEW WELL <input checked="" type="checkbox"/> OLD WELL <input checked="" type="checkbox"/> PROD <input type="checkbox"/> INJ <input type="checkbox"/> WDW <input type="checkbox"/> CUSTOMER ORDER NO.:						
CUSTOMER: L.D. Drilling, Inc		LEASE: Peckance Farms LLC		WELL NO. 1						
ADDRESS		COUNTY: Rush		STATE: KS						
CITY		STATE		SERVICE CREW: Scott, Mike, Bryan						
AUTHORIZED BY: Fred		JOB TYPE: squeeze reefs								
EQUIPMENT#	HRS	EQUIPMENT#	HRS	EQUIPMENT#	4HRS	TRUCK CALLED	DATE	AM	PM	TIME
19843	15						8/8/17	AM		11:30
19918	12						8/8/17	AM		12:20
							8/8/17	AM		2:30
							8/8/17	AM		3:15
						MILES FROM STATION TO WELL				

CONTRACT CONDITIONS: (This contract must be signed before the job is commenced or merchandise is delivered).

The undersigned is authorized to execute this contract as an agent of the customer. As such, the undersigned agrees and acknowledges that this contract for services, materials, products, and/or supplies includes all of and only those terms and conditions appearing on the front and back of this document. No additional or substitute terms and/or conditions shall become a part of this contract without the written consent of an officer of Basic Energy Services LP.

SIGNED: Fred Brown (WELL OWNER, OPERATOR, CONTRACTOR OR AGENT)

ITEM/PRICE REF. NO.	MATERIAL, EQUIPMENT AND SERVICES USED	UNIT	QUANTITY	UNIT PRICE	\$ AMOUNT	
CP100C	Common Cement	SK	65		1040.00	
<del>CP100C</del>	<del>Common Cement</del>	<del>SK</del>	<del>---</del>			
CE 500	Cement Squeeze Manifold	EA	1		500.00	
AK 325	15% HCl Acid	Gal	150		470.00	
<del>CA 135</del>	<del>15% Fluid Loss</del>	<del>Gal</del>	<del>---</del>			
E100	Unit Mileage Pick up	MI	100		450.00	
E101	Heavy Equipment Mileage	MI	200		1500.00	
E113	Prop + Bulk Delivery	TM	310		775.00	
CE 204	Depth Charge 3001 4000'	U/L	1		2160.00	
CE 240	Blending & Mixing Charge	SK	65		91.00	
5003	Service Supervisor	EA	1		175.00	
					SUB TOTAL	7111.00

CHEMICAL / ACID DATA:			

SERVICE & EQUIPMENT	%TAX ON \$	
MATERIALS	%TAX ON \$	
TOTAL		3555.50

SERVICE REPRESENTATIVE: [Signature] THE ABOVE MATERIAL AND SERVICE ORDERED BY CUSTOMER AND RECEIVED BY: Fred Brown  
(WELL OWNER OPERATOR CONTRACTOR OR AGENT)

FIELD SERVICE ORDER NO. \_\_\_\_\_

Customer <i>L.D. Drilling Inc</i>	Lease No. <i>1141-10</i>	Date <i>8/8/17</i>
Lease <i>Recharge Farms</i>	Well # <i>1 0000</i>	
Field Order # <i>15204 A</i>	Station <i>Pratt KS</i>	Casing <i>3 1/2</i>
		Depth <i>3784'</i>
Type Job <i>Supercracks Perfs</i>	Formation <i>24A</i>	Legal Description
		County <i>Rush</i>
		State <i>KS</i>

PIPE DATA		PERFORATING DATA		FLUID USED		TREATMENT RESUME		
Casing Size	Tubing Size	Shots/Ft		Acid	RATE	PRESS	ISIP	
Depth	Depth	From	To	Pre Pad	Max		5 Min.	
Volume	Volume	From	To	Pad	Min		10 Min.	
Max Press	Max Press	From	To	Frac	Avg		15 Min.	
Well Connection	Annulus Vol.	From	To		HHP Used		Annulus Pressure	
Plug Depth	Packer Depth	From	To	Flush	Gas Volume		Total Load	

Customer Representative <i>Fred</i>	Station Manager <i>Justin Westerman</i>	Treater <i>Scott G.</i>
--	--	----------------------------

Service Units <i>38950 84481 14843</i>									
Driver Names <i>Scott Mike</i>	<i>Mike</i>	<i>Mike</i>	<i>Mike</i>	<i>Mike</i>	<i>Mike</i>	<i>Mike</i>	<i>Mike</i>	<i>Mike</i>	<i>Mike</i>

Time	Casing Pressure	Tubing Pressure	Bbls. Pumped	Rate	Service Log
11:30					On Location Safety Meeting
12:00		2300	6.5		Test Tools 3876'
12:20		0		2.5	Load Annulus
12:25	500	0	8	0	Pressure Annulus Shut in
12:35		1700		.7	Start Acid
12:40		1300	3.6	.7	Acid Start Flush
1:00		1800	1.6	1	Increase Rate
1:01		1600	0.5	1.6	Start over Flush
1:04			5		Shut down
				1.5	Pump H <sub>2</sub> O Spacers
			2	1.5	Mix 6.5% Cement
1:25		1000	13.9	2	Start Displacement
1:26		1500	2.25	1.75	Pressure Increase cement on Perfs
1:32		2100	6.5	0	Shut down Max pressure
1:34		0		0	Release Pressure NO Returns
1:36		500		2	Reverse out Tubing
1:45		0	20	0	Shut down
2:00		500		2.5	Wash thru Cement
2:20		0	30	0	Shut down
					Job Complete