1369425

Form CP-111 July 2017 Form must be Typed Form must be signed


TEMPORARY ABANDONMENT WELL APPLICATION

Form must be typed
Form must be signed
All blanks must be complete

Name:								
				Spot Descri	ption:			
Address 1:					Sec	Twp S.	. R 🗌 E 🔲 W	
Address 2:							N / S Line of Section	
City:	State:	Zip: +					E / W Line of Section	
Contact Person:				Dotum:	NAD27 NAD83	, Long:	(e.gxxx.xxxxx)	
Phone:()							GL KB	
Contact Person Email:				Lease Name: Well #: Well first with the control of				
Field Contact Person:								
Field Contact Person Phone							ermit #:	
	//				rage Permit #:			
				Spud Date:		Date Shut-In:		
	Conductor	Surface	Pro	oduction	Intermediate	Liner	Tubing	
Size								
Setting Depth								
Amount of Cement								
Top of Cement								
Bottom of Cement								
asing Fluid Level from Suri	ace	TIOW DC						
Casing Fluid Level from Surf Casing Squeeze(s): (top) Co you have a valid Oil & Ga Cepth and Type: Junk in Type Completion: Cacker Type: Cotal Depth: Geological Date: Formation Name Completed Septimize Septimi	to w / w / w / ss Lease?	sacks of ce No Tools in Hole at	ment, Ca w / Inch Perfo	sing Leaks: sacks Set at: Plug Back Methor	Yes No Dept s of cement Port Fe od: Completic to F	ch of casing leak(s): w Collar: w et on Information Feet or Open Hole Interv		
Casing Squeeze(s): (top) Do you have a valid Oil & Ga Depth and Type:	to w / w / w / ss Lease?	sacks of ce No Tools in Hole at	Perfo	sing Leaks: sacks Set at: Plug Back Methor	Yes No Dept s of cement Port Fe od: Completic to F to F	ch of casing leak(s): w Collar: w et on Information Feet or Open Hole Interview Feet or Open Hole Interview	/ sack of cemen	
Casing Squeeze(s): (top) Do you have a valid Oil & Ga Depth and Type: Junk in J	to w / w / ss Lease?	sacks of ce No Tools in Hole at	Perfo Perfo Perfo Perfo Perfo Perfo Perfo	sing Leaks: sacks sacks Set at: Plug Back Methor ration Interval ration Interval	Yes No Dept s of cement Port Fe od: Completic to F to F	ch of casing leak(s): w Collar: w et on Information Feet or Open Hole Interview Feet or Open Hole Interview	val to Fee	

Mail to the Appropriate KCC Conservation Office:

No. No.	KCC District Office #1 - 210 E. Frontview, Suite A, Dodge City, KS 67801	Phone 620.682.7933
	KCC District Office #2 - 3450 N. Rock Road, Building 600, Suite 601, Wichita, KS 67226	Phone 316.337.7400
	KCC District Office #3 - 137 E. 21st St., Chanute, KS 66720	Phone 620.902.6450
	KCC District Office #4 - 2301 E. 13th Street, Hays, KS 67601-2651	Phone 785.261.6250



Conservation Division District Office No. 1 210 E. Frontview, Suite A Dodge City, KS 67801



Phone: 620-682-7933 http://kcc.ks.gov/

Sam Brownback, Governor

Pat Apple, Chairman Shari Feist Albrecht, Commissioner Jay Scott Emler, Commissioner

November 21, 2017

Bruce Meyer BEREXCO LLC 2020 N. BRAMBLEWOOD WICHITA, KS 67206-1094

Re: Temporary Abandonment API 15-083-21551-00-00 REED E 1 NE/4 Sec.18-22S-23W Hodgeman County, Kansas

Dear Bruce Meyer:

"Your temporary abandonment (TA) application for the well listed above has been approved. In accordance with K.A.R. 82-3-111 the TA status of this well will expire 11/21/2018.

- * If you return this well to service or plug it, please notify the District Office.
- * If you sell this well you are required to file a Transfer of Operator form, T-1.
- * If the well will remain temporarily abandoned, you must submit a new TA application, CP-111, before 11/21/2018.

You may contact me at the number above if you have questions.

Very truly yours,

Michael Maier"